Submit 3 Copies to Appropriate District Office	State of			
		New Mexico latural Resources Department		Form C-
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		ATION DIVISION	WITH I ADVING	Revised March 25, 1
DISTRICT II		Box 2088	WELL API NO. 30-025-02069	
811 South First, Artesia NM 88210 DISTRICT III	Santa Fe New	Mexico 87504-2088	5. Indicate Type of I	P3CA
1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV)	MCXICO 07504-2008		STATE STATE
2040 South Pacheco, Sante Fe, NM 8750	05		6. State Oil & Gas L B-1519	
SUNDRY	NOTICES AND REPORT	IS ON WELLS		
DIFFERENT R	RESERVOIR. USE "APPLICAT	TO DEEPEN OR PLUG BACK TO A	A 7. Lease Name or U	t Agreement Name
	ORM C-101) FOR SUCH PROP		State J	at a Broomont Manie
1. Type of Well: Oil	Caa			
Well	Gas Well Othe	r Injector		
2. Name of Operator			8. Well No.	
	oil Corporation		4	
3. Address of Operator P.O. Box 4 Houston	ГХ 77210-4358	9. Pool name or Wild		
4. Well Location	A1	IA //210-4358	Vacuum; Graybu	rg-San Andres
	660 Feet From The North	Line and660	Feet From The East	Line
Section 22	Township 17S	Range 34E	NMPH	Lea County
	10. Elevation (Sk	now whether DR, RKB, RT, GR, etc.)		
PULL OR ALTER CASING OTHER: Describe proposed or completed	CHANGE PLANS MULTIPLE COMPLETION		LING OPNS. PI	LTERING CASING LUG & ABANDONMENT
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH w Rig up wireline unit and g Dump bail no less than 35' of Run in hole with tubing st 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p	set at 3975', which is within 'OH and rig down wireline u backer fluid	6' of the previous pac nit.	ker setting depth.
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH w Rig up wireline unit and g Dump bail no less than 35' of Run in hole with tubing st POH and lay down tubing 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin	set at 3975', which is within OH and rig down wireline u packer fluid ag in wellbore.	nit.	ker setting depth.
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH well set Rig up wireline unit and generation of the set of the	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin Test by pressuring the cas	set at 3975', which is within OH and rig down wireline u packer fluid ag in wellbore.	nit. m 30 minutes	
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH w Rig up wireline unit and g Dump bail no less than 35' of Run in hole with tubing st POH and lay down tubing Run Mechanical Integrity 2 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin Test by pressuring the cas	set at 3975', which is within OH and rig down wireline u packer fluid ag in wellbore.	nit. m 30 minutes THE COMMISSION BORING ENOR TO	ker setting depth. MUST BE HOTHED 24 MHE BERMAING OF IONS FOR THE C493
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH well set Rig up wireline unit and generating bail no less than 35' of Run in hole with tubing st POH and lay down tubing Run Mechanical Integrity to demonstrate good casing in RDMO. 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p t leaving 1000' of kill strin Test by pressuring the car ategrity.	set at 3975', which is within OH and rig down wireline u backer fluid ag in wellbore. sing to 500 psi for no less tha	nit. In 30 minutes THE COMMESICM HOURD PROR TO MUGGENG OPERAT JO SE APPROVED.	MUST BE NOTIFIED 24 THE BEGINNING OF IONS FOR THE C493
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH w Rig up wireline unit and g Dump bail no less than 35' of Run in hole with tubing st POH and lay down tubing Run Mechanical Integrity 7 to demonstrate good casing in RDMO. 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin Test by pressuring the cas ategrity.	set at 3975', which is within OH and rig down wireline u packer fluid ng in wellbore. sing to 500 psi for no less tha	nit. In 30 minutes THE COMMISSION HOURD PROR TO MUGGING OPERAT JO BE APPROVED. # 2918	MUST BE HOTHED 24 THE BEGINAING OF IONS FOR THE C493 DATE 1930/2000
 Move in and rig up well see Rig up BOP equipment. Unseat packer and POH wells Rig up wireline unit and generating bail no less than 35' of Run in hole with tubing st POH and lay down tubing Run Mechanical Integrity to demonstrate good casing in RDMO. 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin Test by pressuring the cas ategrity.	set at 3975', which is within OH and rig down wireline u backer fluid ag in wellbore. sing to 500 psi for no less tha	nit. In 30 minutes THE COMMISSION HOURD PROR TO MUGGING OPERAT JO BE APPROVED. # 2918	MUST BE NOTIFIED 24 THE BEGINNING OF IONS FOR THE C493
 Move in and rig up well set Rig up BOP equipment. Unseat packer and POH wells Rig up wireline unit and generating bail no less than 35' of Run in hole with tubing st POH and lay down tubing Run Mechanical Integrity of Run Mechanical Integrity of Run Mechanical Integrity of 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin Test by pressuring the cas ategrity.	set at 3975', which is within OH and rig down wireline u backer fluid ag in wellbore. sing to 500 psi for no less tha	nit. In 30 minutes THE COMMISSION HOURD PROR TO MUGGING OPERAT JO BE APPROVED. # 2918	MUST BE HOTHED 04 THE BEGENAING OF IONS FOR THE C-103 DATE 1930/2000 0. (713) 431-1792
 Move in and rig up well see Rig up BOP equipment. Unseat packer and POH wells Rig up wireline unit and generating bail no less than 35' of Run in hole with tubing st POH and lay down tubing Run Mechanical Integrity to demonstrate good casing in RDMO. 	ervice unit. Kill well as ne with tubing. go in hole with CIBP and f cement on top of plug. P tring to TOC. Circulate p g leaving 1000' of kill strin Test by pressuring the car ategrity.	set at 3975', which is within OH and rig down wireline u backer fluid ag in wellbore. sing to 500 psi for no less tha	nit. In 30 minutes THE COMMISSION HOURD PROR TO MUGGING OPERAT JO BE APPROVED. # 2918	MUST BE HOTHED 24 THE BEGINAING OF IONS FOR THE C493 DATE 1930/2000

and the second