

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002502136
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	011126
7. Lease Name or Unit Agreement Name	
West Vacuum Unit	
8. Well No.	4
9. Pool name or Wildcat	Vacuum <i>OB-SA</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER ☒ injection

2. Name of Operator
Texaco E&P Inc.

3. Address of Operator
P.O. Box 3109 Midland, TX 79702

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line

Section 28 Township 17S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOCD of intent to plug & abandon well prior to moving.
2. TIH w/5½ cmt. retainer to @ 4400 pump @ 150 sxs class C cmt. into San Andres zone 4505-4708. Unsting & cap CIGR w/20 sxs cmt. f/4400-4300.
3. POOH w/tub to 3900. Spot ~~20~~ sxs cmt. f/3900-3800 (WOC & tag) Queens
4. POOH w/tub to 2900. Spot ~~20~~ sxs cmt. f/2900-2800 (Yates) WOC & tag.
5. POOH w/tub to 2700. Spot ~~20~~ sxs cmt. f/2700-2600 (base of Salt)
6. POOH w/tub to 1800. Spot ~~20~~ sxs cmt. f/1800-1700 (top of salt)
7. POOH w/tub to 454. Spot ~~20~~ sxs cmt. f/454-354 (8-5/8" shoe)
8. POOH w/tub to 50'. Spot 10 sxs cmt. f/50-surface.
9. Cut off wellhead & cap & install dryhole marker.

MINIMUM 25 SXS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE RJ Harding III TITLE Operations Engineer DATE 10-5-94

TYPE OR PRINT NAME RJ Harding III

TELEPHONE NO. 915-688-4816

(This space for State Use)

On file Signed by
Paul J. Smith
Geologist

OCT 12 1994

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.