



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

DIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE

December 12, 1997

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 86241-1980 (505) 363-6161

. . **

Rover Operating, Inc. 903 18th Street, Suite 224 Plano, Texas 75074

Pusseur charts OK Museur 4E

Re: Phillips Lea (SWD) #4-M, Sec. 31, T17S, R34E

Gentlemen:

We have received your request for approval to make the repairs on the above referenced well.

You may start the repairs on the well as soon as you determine the location of the holes in the casing, and the proper method to be used to bring the well into compliance with Oil Conservation Division standards.

We request 24 hours notice prior to the procedure in order to witness the operation and the pressure test upon completion of repairs.

After the repairs are completed, you are to submit a subsequent report (C-103) confirming the type of repairs, such as depth of the holes, cement used to squeeze off the leaks and/or other procedures used to make the repairs.

Very truly yours

OIL CONSERVATION DIVISION

his Williams

Chris Williams Supervisor, District I

CW:bp

cc: William J. LeMay File

David Hanger 972-422-9029 Hover Operating Phillips Liel Lease well 1-8 Well #4 failed pressure test - pent mechanical Request te repair But hasn't heard anything needs Chriss approval I wants to finesh this month 31-175-34E