

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P.O. Box Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002502186
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	858150
7. Lease Name or Unit Agreement Name	WEST VACUUM UNIT
8. Well No.	17
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>33</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER:	Temporary abandon extension	<input checked="" type="checkbox"/>	

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPERATION	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER:		<input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify OCD 24 hours prior to commencing work.
- 2) Move in and rig up pulling unit.
- 3) TIH with 2 7/8" workstring and 5 1/2" Pkr.
- 4) Check casing's integrity. In case of failure take proper action.
- 5) Circulate hole with inhibited fluid and chart as per NMOCD guidelines, 500# for 30 min.
- 6) Request temporary abandoned extension to 9/1/2001.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Siamak Safargar TITLE Prod. Engineer DATE Sep. 14, 98  
TYPE OR PRINT NAME M. Siamak Safargar Telephone No. 397-0429

(This space for State Use)

APPROVED BY CHRIS WILLIAMS TITLE SUPERVISOR DATE 9/14/98  
CONDITIONS OF APPROVAL, IF ANY:

TEXACO  
West VAC unit

#17-H  
33-1734

AS we pumped  
TR6 Jumbled at hole  
30' to slips in wellbore  
Did not continue  
TEST

CP

4-4-97

6 NIGHT