

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02235
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-155
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	69
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4015' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4015' DF

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	OTHER:	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPERATION	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER:	<input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Texaco intends to plug and abandon the subject well. The intended procedure is as follows:

- 1) NOTIFY OCD BEFORE COMMENCING OPERATIONS. MIRU. PUWH & TIH OPEN ENDED TO RBP @ 4052'. RU CEMENTERS AND WASH SAND OFF TOP OF PLUG & DUMP 25 SXS CEMENT ON PLUG. POOH & WOC. TIH & TAG CMT PLUG. CIRC 40 BBLS OF SALT GEL MUD (MINIMUM 9.5# BRINE WITH 25#/BBL OF GEL) TO FILL 5 1/2" CSG BETWEEN RBP @ 4052' & CSG PART @ 2632'.
2. POOH & SET BTM OF TBG AT ABOUT 2950'. SPOT 25 SX OF CMT & TOH W/TBG.
3. TIH W/5 1/2" CMT RET TO ABOUT 2570'. ESTABLISH PUMP IN RATE & PRESSURE AND SQZ 100 SXS CMT INTO PARTED CSG. STING OUT OF RET & DUMP 25 SX CMT ON RET. POOH & WOC. TIH & TAG CMT PLUG. CIRC 9.5# BRINE MUD TO FILL CSG.
4. POOH TO TOP OF SALT SECTION AT ABOUT 1630' & SPIT A 25 SX PLUG. TOH W/TBG.
5. SPOT 10 SX CMT SURF PLUG. CUT CSG BELOW SURF & INSTL P&A MARKER. CLEAN SURF LOCATION.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 6/16/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY

DATE