## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| us, or corits acctives |          |
|------------------------|----------|
| DISTRIBUTION           |          |
| BANTA FE               | <u> </u> |
| FILE                   |          |
| U.S.O.E.               |          |
| LAND OFFICE            |          |
| OPERATOR               | ]        |

## LIL CONSERVATION DIVISION

|   | P. O. BOX 2088  |   |
|---|---|---|
| BANTA FE                                | SANTA FE, NEW MEXICO 87501  | Revised 19-1                                  |
| FILE                                    |   | 5a. Indicate Type of Lease                    |
| U.S.G.S.                                |   | State X Fee                                   |
| DERATOR                                 |   | 5. State Oil & Gas Lease No.                  |
| OPERATOR                                |   | B-155   |
| EIHT 3EU TOH 00)                        | SUNDRY NOTICES AND REPORTS ON WELLS  LIFORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  JEE "APPLICATION FOR PERMIT —" (FORM C. 101) FOR SUCH PROPOSALS.)   |   |
| OIL [V] 6.                              | AB OTHER-   | 7. Unit Agreement Name<br>Central Vacuum Unit |
| lame of Operator                        |   | 8. Farm or Lease Name                         |
| EXACO Inc.                              |   | Central Vacuum Unit                           |
| ddress of Operator                      |   | 9. Well No.                                   |
| . 0. Box 728.                           | Hobbs, New Mexico 88240   | 66  |
| ocation of Well<br>H                    | 7/0   | Vacuum Grayburg Wildom<br>San Andres          |
| UNIT LETTER                             |   |   |
| North                                   | LINE, SECTION 36 TOWNSHIP 17-S RANGE NMP  |   |
| mmm                                     | 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County                                    |
|   | 4000' (GR)  | Lea   |
| REFORM REMEDIAL WORK                    | COMMENCE DRILLING OPHS.   | ALTERING CASING PLUG AND ABANDONMENT          |
| OTHER                                   | CHANGE PLANS  OTHER  OTHER  Completed Operations (Clearly state all pertinent details, and give pertinent dates, include 03.  | ing estimated date of starting any propu      |
| OTHER                                   | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BAL  | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'. SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BAL   | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BAL  | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BALROCK SALT. FLUSH W/FORMATION WATER. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BAL  | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BALROCK SALT. FLUSH W/FORMATION WATER. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BALROCK SALT. FLUSH W/FORMATION WATER. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 160 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BALROCK SALT. FLUSH W/FORMATION WATER. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 110 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BALROCK SALT. FLUSH W/FORMATION WATER. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |
| Describe Proposed or work) SEE RULE 160 | RIGGED UP. INSTALL BOP. PULL TUBING AND SUBME CLEAN OUT TO 4728'.  SET PKR @ 3528'. ACIDIZE OPEN-HOLE SECTION W/15,000 15%NEFE GELLED ACID, 1800# MOTH BALROCK SALT. FLUSH W/FORMATION WATER. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN | RSIBLE PUMP.<br>4098-4728'<br>LS AND 1800#    |

DRIGINAL SIGHED BY JEEPY SEXTON

NOV 29 1984