

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|                                                                                                     |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO.<br>3002502940                                                                          |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>011122                                                              |
| 7. Lease Name or Unit Agreement Name<br>Central Vacuum Unit                                         |
| 8. Well No.<br>2                                                                                    |
| 9. Pool name or Wildcat<br>Vacuum Grayburg San Andres                                               |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. Name of Operator  
Texaco E&P Inc.  
3. Address of Operator  
P.O. Box 3109 Midland, TX 79702

4. Well Location  
Unit Letter B : 330 Feet From The North Line and 2310 Feet From The East Line  
Section 30 Township 17S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3983 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NMOCD of intent to plug & abandon prior to moving unit on well.  
Note: well has 5½" CIBP @ 4200 w/35 of cmt.
2. TIH w/tub to 3900. Spot ~~20~~ sxs cmt plug f/3900-3800 (Queens) WOC & tag.
3. POOH to 3000. Spot 65 sxs cmt plug f/3000-2700 (Yates Btm. SAH WOC & tag.
4. POOH to 1800. Spot ~~20~~ sxs cmt plug f/1800-1700 (top salt) WOC & tag.
5. POOH to 1725. Spot 25 sxs cmt. plug f/1725-1625 (8-5/8 shoe)
6. POOH to 400. Spot ~~20~~ sxs cmt. plug f/400-300
7. POOH to 50. Spot 10 sxs cmt plug f/50-surface
8. Cut off wellhead & weld on cap & install dry hole marker.

25 SXS MINIMUM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE RJ Harding III TITLE Operations Engineer DATE 10-5-94

TYPE OR PRINT NAME RJ Harding III TELEPHONE NO. 915-688-4816

(This space for State Use)

OCT 12 1994

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED BY  
DATE  
FOR THE