STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO OF COMES RECEIVED

OIL CONSERVATION DIVISION P O BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103

DISTRUCTION		SANTA FE, NEW	MEXICO 87501			rm C-10		
SANTA FE					ĸe	vised 10	-1-78	
FRE								
U.S.G.S				Sa Indicate	Type of Lease			
LAND OFFICE				State		Fee		
OPERATOR				5 State Oil	& Gas Lease No	,		
			02072					
	SUNDRY	API No. 30-025- NOTICES AND REPORTS ON W		B-15	/6-3		77777	
(DO NOT 351 THIS		OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK			//////	$\prime \prime \prime \prime \prime$	$\prime \prime \prime \prime \prime \prime$	
		TION FOR PERMIT . * (FORM C-101) FOR SUCH PRO				711	1111	
11	GAS			7 Unit Agr	eement Name			
				East Vacuum Gb/Sa Unit				
12 Name of Operator				B Farmor	eate Name			
Phillips Petroleum Company								
					East Vacuum Gb/SA Unit			
13 Address of Operator					9. Well No. Tr. 3229			
4001 Penbrook Street, Odessa, Texas 79762					002			
14 Location of Well					10. Field and Pool, or Wildcat			
UNIT LETTER M . 660 FEET FROM THE SOUTH LINE AND 660 FEET FI					Vacuum Gb/SA			
UNIT LETTER M	66	U FEET FROM THE SOUTH	INE AND FEET FRO	777777 M	minn		<u></u>	
		22 17 0				\cdots	////	
THE West: LINE SECTION 32 TOWNSHIP 17-S RANGE 35-E NI				•//////	//////	(11)		
				-7////	7777777	777	$\overline{\eta}\overline{\eta}$	
15. Elevation (Show whether DF, RT, GR, etc.)				12. County		////	////	
	71117	4000' RKB		Lea		\cdots	()))	
16 Ch	eck Appr	opriate Box To Indicate Nature	of Notice Report or O	ther Data		<u></u>	<u> </u>	
			-					
NOTICE OF I	NIENIIC	IN TO:	SUBSEQ	UENT REPOR	RT OF:			
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASH	NC	Π	
		_	COMMENCE DRILLING OPHS.	n n			<u>с</u>	
					PLUG AND ABA	NDONME	ит 🛄	
			CASING TEST AND CEMENT JOB	IJ				
	L, <u>log</u> ,	cement liner, perf 🖾	OTHER					
<u> </u>								
work) SEE RULE 1103.	leted Opera	ations (Clearly state all pertinent detai	is, and give pertinent dates,	including estin	ated date of st	arting a	iny prope	
•								
Proposed procedure	e to de	epen well, run open hole	e logs, run & cem	ent liner,	perforat	e		
and stimulate well	L:							
	_							
RU DDU. Pull rods	and pu	mp. Install BOP. POOH wi	ith production tu	bing. RU	reverse			
unit, deepen 4-3/2	i" open	hole from 4640'-4800'.						
Run Induction-GR-C	Laliper	and FDC-CNL-GR-Caliper	logs.					
Run 4'' 10/46# J-55	5 F.J.	liner and cement with ca	aliper plus 30% ex	xcess of (lass "C"	cemer	nt.	
			_					
Perforate selected	linter	vals in the San Andres f	formation from ±4	140'-4700'	•			
Stimulate perforat	ed inte	ervals with 15% NEFE HCI	acid, swab to c	lean up we	ell. Insta	11		
		sized according to well		ormance.				
18 I hereby certify that the information	above is true	and complete to the best of my knowledge and b	slief.					
hal _	10							
SIGNED - TUR	h u	J. Nueller mu Enginee	ring Supervieor	Reserv	DATE 11-	15-88	2	
				- <u></u>			•	
ORIGINAL SIGNE					MAN	69	1926	
APPROVED BY DISTRICT	I SUPERV				DATE	* 6	NAAA	