Submit 3 Copies to Appropriate District Office	Energy, er	State of New Mexico rals and Natural Resources Departmer	t Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240)	SERVATION DIVISION P.O. Box 2088	WELL API NO. 30-025-03177
DISTRICT II P.O. Drawer DD, Anesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410		5. Indicate Type of Lease STATE FEE X	
		6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS			
DIFFERENT	OR PROPOSALS TO DRI RESERVOR. USE "APP ORM C-101) FOR SUCH	ILL OR TO DEEPEN OR PLUG BACK TO PLICATION FOR PERMIT* PROPOSALS 1	A 7. Lease Name or Unit Agreement Name
1. Type of Well:			Northeast Pearl Queen
OL GAS WELL 2. Name of Operator	ú [_]	onea Water Injection	Unit 8. Well No.
	Oil & Gas Con	mpany	5
3. Address of Operator			9. Pool name or Wildcat
4. Well Location	Box 51311, Mie	dland, TX 79710	Pearl (Queen)
Unit LetterA ;	660 Feet From Th	e North Line and 6	60 Feet From The East Line
Section 22	Township	19-S Range 35-E	NMPM Lea County
	//////////	evation (Show whether DF, RKB, RT, GR, etc.) 791 KB	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Cł		Box to Indicate Nature of Notice	, Report, or Other Data
	F INTENTION TO		UBSEQUENT REPORT OF
NOTICE O			
		C-2	
ERFORM REMEDIAL WORK		ABANDON X REMEDIAL WORK	
PERFORM REMEDIAL WORK		ABANDON X REMEDIAL WORK	
ERFORM REMEDIAL WORK		ABANDON X REMEDIAL WORK	ALTERING CASING
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING		ABANDON X REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER:	PLUG AND CHANGE P	ABANDON X REMEDIAL WORK PLANS COMMENCE DRILL CASING TEST AND OTHER:	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed work) SEE RULE 1103. The su	PLUG AND CHANGE P CHANGE P Operations (Clearly state of bject well had and 4 1/2" ca	ABANDON REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: all perturent details, and give perturent dates, if as 8 5/8" surface cas	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete work) SEE RULE 1103. The su to surface to be at 36 It is	PLUG AND CHANGE P CHANGE P Openations (Clearly state of bject well ha and 4 1/2" ca 94' suspected tha lugging is ar	ABANDON REMEDIAL WORK PLANS COMMENCE DRILL CASING TEST AND OTHER: all pertiment details, and give pertiment dates, is as 8 5/8" surface cas asing set at 5049' to at the 4 1/2" casing	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed work) SEE RULE 1103. The su to surface to be at 36 It is surface. P of this pro 1. Mo 2. Se 3. Pe 4. Se	PLUG AND CHANGE P CHANGE Change	ABANDON REMEDIAL WORK PLANS COMMENCE DRILL CASING TEST AND OTHER: all perturent details, and give perturent dates, if as 8 5/8" surface cas asing set at 5049' to at the 4 1/2" casing nticipated to begin in g-up pulling unit. Proprox 4750 (top of Pent 2" csg at 400squeet ht plug at surface.	ALTERING CASING PLUG AND ABANDONMENT D CEMENT JOB ncluding estimated date of starting any proposed ing set at 167' cemented p of cement is estimated is leaking at 77' from mmediately upon approval
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete work) SEE RULE 1103. The su to surface to be at 36 It is surface. P of this pro 1. Mo 2. Se 3. Pe 4. Se 5. In	PLUG AND CHANGE P CHANGE P CHANGE P Change P C d Operations (Clearly state of bject well had and 4 1/2" ca 94' suspected tha lugging is ar cedure: ve in and rig t CIBP at app rforate 4 1/2 t 15 sx cemer stall dry hol	ABANDON A REMEDIAL WORK PLANS COMMENCE DRILL CASING TEST AND OTHER: all perimeni details, and give perimeni dates, if all perimeni details, and give perimeni dates, if as 8 5/8" surface cas asing set at 5049' to at the 4 1/2" casing nticipated to begin in g-up pulling unit. Proprox 4750 (top of Peni 2" csg at 400squeet ht plug at surface. le marker.	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D CEMENT JOB ACLING OPNS. PLUG AND ABANDONMENT D CEMENT JOB ACLING at JOB PLUG AND ABANDONMENT COMMENT JOB ACLING OPNS. PLUG AND ABANDONMENT ACLING OPNS. PLUG AND ABANDONMENT ACLING OPNS. PLUG AND ABANDONMENT ACLING OPNS. PLUG AND ABANDONMENT COMMENT JOB ACLING AND ABANDONMENT ACLING OPNS. ACLING ACLING AND ABANDONMENT ACLING ACLING ACLING ACLING AND ABANDONMENT ACLING ACLING AND ABANDONMENT ACLING A
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete work) SEE RULE 1103. The su to surface to be at 36 It is surface. P of this pro 1. Mo 2. Se 3. Pe 4. Se 5. In 1 hereby certify that the information form	PLUG AND CHANGE P CHANGE Change Cha	ABANDON A REMEDIAL WORK PLANS COMMENCE DRILL CASING TEST AND OTHER: all perimeni details, and give perimeni dates, if all perimeni details, and give perimeni dates, if as 8 5/8" surface cas asing set at 5049' to at the 4 1/2" casing nticipated to begin in g-up pulling unit. Proprox 4750 (top of Peni 2" csg at 400squeet ht plug at surface. le marker.	ALTERING CASING PLUG AND ABANDONMENT D CEMENT JOB ncluding estimated date of starting any proposed ing set at 167' cemented p of cement is estimated is leaking at 77' from nmediately upon approval ull 2 3/8 tubing out of hole rose). Cap w/ 35 sx cement. ze/circ. cement to surface.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete work) SEE RULE 1103. The su to surface to be at 36 It is surface. P of this pro 1. Mo 2. Se 3. Pe 4. Se 5. In 1 hereby certify that the information for sionature	PLUG AND CHANGE P CHANGE Change Cha	ABANDON A REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: all perimeni details, and give perimeni dates, if all perimeni details, and give perimeni dates, if as 8 5/8" surface cas asing set at 5049' to at the 4 1/2" casing nticipated to begin in g-up pulling unit. Pro- prox 4750 (top of Peni 2" csg at 400squeen 1 plug at surface. le marker. est of my knowledge and belief	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT D CEMENT JOB ACLING OPNS. PLUG AND ABANDONMENT D CEMENT JOB ACLING at JOB PLUG AND ABANDONMENT COMMENT JOB ACLING OPNS. PLUG AND ABANDONMENT ACLING OPNS. PLUG AND ABANDONMENT ACLING OPNS. PLUG AND ABANDONMENT ACLING OPNS. PLUG AND ABANDONMENT COMMENT JOB ACLING AND ABANDONMENT ACLING OPNS. ACLING ACLING AND ABANDONMENT ACLING ACLING ACLING ACLING AND ABANDONMENT ACLING ACLING AND ABANDONMENT ACLING A
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DTHER: 12. Describe Proposed or Complete work) SEE RULE 1103. The su to surface to be at 36 It is surface. P of this pro 1. Mo 2. Se 3. Pe 4. Se 5. In 1 hereby certify that the information foor SIONATURE TYPE OR FRINT NAME CONSTRUCTION	PLUG AND CHANGE P CHANGE Change	ABANDON A REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: all perimeni details, and give perimeni dates, if all perimeni details, and give perimeni dates, if as 8 5/8" surface cas asing set at 5049' to at the 4 1/2" casing nticipated to begin in g-up pulling unit. Pro- prox 4750 (top of Peni 2" csg at 400squeet nt plug at surface. le marker. est of my knowledge and belief Owner	ALTERING CASING PLUG AND ABANDONMENT D CEMENT JOB ncluding estimated date of starting any proposed ing set at 167' cemented p of cement is estimated is leaking at 77' from nmediately upon approval ull 2 3/8 tubing out of hole rose). Cap w/ 35 sx cement. ze/circ. cement to surface.