

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1553

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State "E" Tract 18
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 16
4. Location of Well UNIT LETTER <u>D</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>17-S</u> RANGE <u>36-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Lovington Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3848' RDB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon subject well as follows: (Notify NMOCD 24 hours before starting work.).  
Pull tubing and anchor. Set a cast iron bridge plug at 8100' and cap with 35' class C neat cement. Spot 25 sacks class C neat cement. Perforate 7" casing string at 4500' with 4 JSPF. Set a cement retainer at 4400'. Pump 330 sacks cement behind 7" casing string. (Top of cement will be apx. 1600'.) Cap cement retainer with 35' of cement. Perforate through 7" and 9-5/8" casing string at 1450'. Set a cement retainer at 1350'. Circ. cement behind 7" casing string. Close valve and circ. cement behind 9-5/8" casing string. Cap the retainer and pull out of hole. Spot 15 sacks class C neat cement at surface. Erect PXA marker and cap well. (Note: Place mud consisting of 10# brine and 25# gel/bbl between all plugs.

0+5-NMOCD,H 1-R.E. Ogden, HOU Rm. 21.150 1-F.J. Nash, HOU Rm. 4.206 1-CLF 1-GDH,bldg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Sorman TITLE Asst. Admin. Analyst DATE 3-13-84

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

MAR 15 1984

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 13 1984  
C.D.  
HOBBS OFFICE