CASE NO. 10154 Order No. R-9431 Page -6-

fluid to the satisfaction of the supervisor of the Hobbs district office of the Division. will assure that these wellbores will not serve as a conduit for migration of injected (5) Prior to initiating injection operations within one-half mile of any of the wells shown on Exhibit "D", the applicant shall re-plug said wells in a manner which

EXHIBIT "D" CASE NO. 10154 ORDER NO. R-9431

INADEQUATELY PLUGGED AND ABANDONED WELLS

OK.	
Operator Tidewater Associated Oil Co. Cities Service Getty Oil Co. Getty Oil Co. Mag noli a Petroleum Co.	
Lease H.T. Monteith State AE State "M" State "P" State "R"	
Well No. 1 2 3 5 3	
Location 1650' FSL - 2335' FWL 3630' FNL - 4290' FEL 1650' FSL - 1650' FEL 330' FSL - 330' FWL 660' FNL - 660' FEL	
Sec-Twp-Rge 25-16-36 36-16-36 32-16-37 02-17-36	

Recy