STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. of Comits Acctives	T	
DISTRIBUTION		
SANTA FE		
PILE	T-	
U.S.G.S.		
LAHO OFFICE	1	
OFFRATOR	1	

OIL CONSERVATION DIVISION

P. O. BOX 2088

ATMA	FF.	NEW MEXICO 87501

Form C-103 -

SANTA FE	ANTA FE, NEW MEXICO 87501	Revised 10-1-
U.S.G.S.		Su. Indicute Type of Lease
LAHO OFFICE		State Fee
POTAMBER		5, State Off & Gas Leuse No.
SUNDRY NOTICES A	ND REPORTS ON WELLS	B-4119
OD NOT USE THIS FORM FOR PROPOSALS TO CRILL COURT SERVIT -	ND REPORTS ON WELLS ON TO DEFEN OF PLUG BACK TO A DIFFERENT RESERVOIR. " (FORM C-101) FOR SUCH PROPOSALS.)	
OIL X GAS OTHER-		7. Unit Agreement Nume
ame of Operator		West Lovington Uni
TEXACO, INC.		west Lovington Uni
ddrass of Operator P. O. Box 728, Hobbs, Ne	Warden 990ho	9. Well No.
ocation of Well		10. Field and Pool, or Wildest
UNIT LETTER K , 1980 FEET F	ROM THE West LINE AND 1980 FEET	10. Field and Pool, or Wildcat Lovington San And
THE South LINE, SECTION 5	TOWNSHIP 17-S RANGE 36-E N	MPM.
[[]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]	evation (Show whether DF, RT, GR, etc.)	12, County
	3903' (GR)	Lea
Check Appropriate B	ox To Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION TO		ENT REPORT OF:
PORM REMEDIAL WORK	LUG AND ABANCON REMEDIAL WORK	
PORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
OR ALTER CASING	HANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
TUFE		
1. Rigged up. Pull rods 8	state all pertinent details, and give pertinent dates, inclu pump. Install BOP. 20' & pull 4720' than Eigh at	
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Aciding % NEFE acid in 2 state.	& pump. Install BOP. 20' & pull 4720' tbg. Fish state ize open-hole section 4740'-56	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Aciding % NEFE acid in 2 state.	& pump. Install BOP. 20' & pull 4720' tbg. Fish straight open-hole section 4740'-50 ages using 500# rock salt between the contract wall	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Aciding % NEFE acid in 2 state.	& pump. Install BOP. 20' & pull 4720' tbg. Fish straight open-hole section 4740'-50 ages using 500# rock salt between the contract wall	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Aciding % NEFE acid in 2 state.	& pump. Install BOP. 20' & pull 4720' tbg. Fish straight open-hole section 4740'-50 ages using 500# rock salt between the contract wall	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Acidil 15% NEFE acid in 2 sta 5. Install Pumping equipm 6. Remedial work Unsucces	& pump. Install BOP. 20' & pull 4720' tbg. Fish strict ize open-hole section 4740'-50 ages using 500# rock salt betweent. Test well. assful. Workover completed shut	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Aciding % NEFE acid in 2 state.	& pump. Install BOP. 20' & pull 4720' tbg. Fish strict ize open-hole section 4740'-50 ages using 500# rock salt betweent. Test well. assful. Workover completed shut	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Acidil 15% NEFE acid in 2 sta 5. Install Pumping equipm 6. Remedial work Unsucces	& pump. Install BOP. 20' & pull 4720' tbg. Fish state open-hole section 4740'-56 ages using 500# rock salt between the section ages ages using 500# rock salt between the section ages ages ages ages ages ages ages ages	uck tbg & pull same. 025' w/2000 gals ween stages. t-IN 8-5-82,
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Acidil 15% NEFE acid in 2 sta 5. Install Pumping equipm 6. Remedial work Unsucces	& pump. Install BOP. 20' & pull 4720' tbg. Fish strict ize open-hole section 4740'-50 ages using 500# rock salt betweent. Test well. assful. Workover completed shut	uck tbg & pull same. 025' w/2000 gals ween stages.
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Aciding 15% NEFE acid in 2 states and a state of the	& pump. Install BOP. 20' & pull 4720' tbg. Fish state open-hole section 4740'-56 ages using 500# rock salt between the section ages ages using 500# rock salt between the section ages ages ages ages ages ages ages ages	uck tbg & pull same. 025' w/2000 gals ween stages. t-IN 8-5-82,
1. Rigged up. Pull rods & 2. Cut stuck tubing @ 472 3. Clean out to 5025'. 4. Set pkr @ 4650'. Acidil 15% NEFE acid in 2 sta 5. Install Pumping equipm 6. Remedial work Unsucces	& pump. Install BOP. 20' & pull 4720' tbg. Fish state open-hole section 4740'-56 ages using 500# rock salt between the section ages ages using 500# rock salt between the section ages ages ages ages ages ages ages ages	uck tbg & pull same. 025' w/2000 gals ween stages. t-IN 8-5-82,

AUG 6 1982