

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-4120	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
TEXACO Inc.		West Lovington Unit
3. Address of Operator		9. Well No.
P O Box 728, Hobbs, New Mexico 88240		52
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM		Lovington San Andres
THE East LINE, SECTION 7 TOWNSHIP 17-S RANGE 36-E NMPM.		West
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4002' (DF)		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install 30P
2. Cut 5 1/2" Csg @ approx. 2700' & pull same.
3. Spot 25 sx. Cement plug from 2750'-2650'.
4. Spot 30 sx. cement plug from 2046'-1946'.
5. Perforate 8 5/8" Csg. W/4-JS @ 350'.
6. Set Cement retainer @ 200'.
7. Cement to surface through perforations @ 350' W/400 sx. Cement.
8. Spot 30 sx. Cement plug from 100' - surface.
9. Set Dry Hole Marker & Clean location.
10. Plug & Abandon Well.

SET 100' @ 1946 AT 4000'

THIS COPY MUST BE NOTIFIED 24
HOURS BEFORE THE BEGINNING OF
OPERATIONS FOR THE CHOS
WELL PLUG

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Mgr. DATE 5-25-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

MAY 27 1983

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAY 26 1983
O.C.D.
HOBBS OFFICE