

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05432
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-8165
7. Lease Name or Unit Agreement Name Southern Union State
8. Well No. 1
9. Pool name or Wildcat Midway ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Marks & Garner Production Company
3. Address of Operator P O Box 70, Lovington, NM 88260	4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>17S</u> Range <u>37E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-29-92 Set cast iron BP 8750 25' cement on top, shoot casing 6500 spot 50 sacks, plug, shoot casing 3994 and pull spot 50 sacks in and out, tag 3954, spot 50 sacks plug 3600 - 3500.

12-02-92 Shoot 8 5/8 at 900 laid down pump 80 dacks 940', tag plug 780'..

12-12-92 Pump 80 sacks 360'

12-13-92 Tag plug 240'

12-17-92 Install dry hole marker - 10 sacks cement

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James H. Garner TITLE Partner DATE 02-02-93  
TYPE OR PRINT NAME James H. Garner TELEPHONE NO. 396-5326

(This space for State Use)

APPROVED BY James H. Garner TITLE OIL & GAS INSPECTOR DATE FEB 05 1993  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

11 FEB 03 1993

CCD WORKS OFFICE