

U. S. M. OIL CONSERVATION
P. O. BOX 1980

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 41-R1454

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Saltwater Disposal	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR HARRIS, BOYLE & STEWART	8. FARM OR LEASE NAME Young Federal
3. ADDRESS OF OPERATOR Box 1840 Graham, Texas 76046	9. WELL NO. 4
4. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	10. FIELD AND POOL, OR WILDCAT Young Green
5. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	11. SEC. T., R., M., OR BLM. AND SURVEY OR AREA C-17-188-32E
6. PERMIT NO. 1 - Section 17 - T188-32E	12. COUNTY OR PARISH Lea
13. ELEVATIONS (Show whether DF, RT, GR, etc.)	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE IN DETAIL THE OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any operations. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the work.)

Intend to plug and abandon subject well as follows:

1. Set C.I.B.P. 2 3/4" x 35' cement on top of plug.
1. Set 160' cement plug (50' in & 50' out) in 5 1/2" casing sunk.
3. Set 100' cement plug (50' in & 50' out) in 6 3/8" surface shoe. (Shoe 2 452')
4. Set 15 cm. cement plug at top of surface and install dry hole marker.



U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO


18. SIGNATURE OF THE PERSON MAKING THE STATEMENT AND CORRECT

SIGNED: *[Signature]* TITLE: Production Superintendent DATE: June 15, 1982

(This space for Federal or State office use)

APPROVED BY: _____ TITLE: _____ DATE: _____

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side