

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-2531</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>		7. Unit Agreement Name	
2. Name of Operator <b>Penrose Production Company</b>		8. Farm or Lease Name <b>Southern Pet. State</b>	
3. Address of Operator <b>Box 988, Eunice, New Mexico</b>		9. Well No. <b>2</b>	
4. Location of Well UNIT LETTER <b>07</b> , <b>2310</b> FEET FROM THE <b>West</b> LINE AND <b>330</b> FEET FROM THE <b>South</b> LINE, SECTION <b>24</b> TOWNSHIP <b>17 S</b> RANGE <b>35 E</b> NMPM.		10. Field and Pool, or Wildcat <b>Undesignated</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>3920 GR</b>		12. County <b>Lea</b>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull 4840' 4½ Csg.  
10 Sx Plug at bottom  
25 Sx plug at 4800'  
25 Sx plug at 466' - Pull 90' 8 5/8" pipe.  
30 Sx Plug at 90'  
10 Sx Plug at top

Set Marker & Level Location for Inspection

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.E. Enright TITLE Office Manager DATE 8-28-67  
7-17-67

APPROVED BY John W. Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: