Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

PLUG AND ABANDONMENT

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONS

DISTRICTI P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO.		
	30-025-20046		
	5. Indicate Type of Lease		
	STATEXXX FEE		
	6. State Oil & Gas Lease No.		
	B-155		

	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL WELL OTHER Condensate	B-155 7. Lease Name or Unit Agreement Name Vacuum Glorieta West Unit
2. Name of Operator	
Texaco E & P Inc	8. Well No. 130
3. Address of Operator	
P.O. Box 3109 Midland, Texas 79702	9. Pool name or Wildcat Vacuum Glorieta
4. Well Location	vacuum Giorieta
Unit Letter N : 519 Feet From The South Line and 1839	Feet From The West Line
Section 36 Township 17-S Range 34-E	VMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Re	nort or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON XX REMEDIAL WORK	ALTERING CASING

PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

COMMENCE DRILLING OPNS.

- 15. Set tbg @2805' & spot 10 sx cement (Yates, Base of Salt)
- 16. If cement tags @2580' pull to 1740' & spot 10 sx cement (WOC & tag) shoe plug
- 17. If plug is @1455' \pm spot surface plug from 30' w/5 sx cement

CHANGE PLANS

18. N.D. BOP - R.D.M.O.

TEMPORARILY ABANDON

work) SEE RULE 1103.

19. Cut off wellhead, install dryhole marker & clean location

hereby certify that the afformation above is true and complete to the best of my knowledge a	mme Engineer	DATE 2/12/98
YPE OR PRINT NAME Dave Deax		TELEPHONE NO.
hus space for State Use) SIGNED BY		
ORIGINAL SIGNED BY (FARY WINK TROVED BY FIRST TO THE PROPERTY OF THE PROPERT		
TROVED BY	ITTLE	DATE DATE

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT

P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA	TION DIVISION	WELL
DISTRICT II	P.O. Box 2088		WELL API NO.
P.O. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 87504-2088		30-025-20046	
DISTRICT I'I			5. Indicate Type of Lease STATE XX
1000 Rio Brazos Rd., Aztec, NM 87410	0		6. State Oil & Gas Lease No.
OLUMB TO THE TANK THE			B-155
(DO NOT USE THIS FORM FOR I	TICES AND REPORTS ON	WELLS	
(DO NOT USE THIS FORM FOR F	SERVOIR. USE "APPLICATION FO	EPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
(FUHM	C-101) FOR SUCH PROPOSALS) PERMIT	Vacuum Glorieta West Unit
1. Type of Well:		,	-
MEIT MEIT	OTHER Cor	ndensate	
2. Name of Operator			9 11/-11 NI
Texaco E & P Inc 3. Address of Operator			8. Well No. 130
	_		9. Pool name or Wildcat
P.O. Box 3109 Midland 4. Well Location	, Texas 79702		Vacuum Glorieta
	10		
Onk Letter N :	Feet From The South	Line and183	9 Feet From The West Lin
Section 36			
	Township 17-S	Range 34-E sether DF, RKB, RT, GR, etc.)	NMPM Lea County
		einer Dr., KKB, KI, GK, elc.)	
II. Check	Appropriate Poy to India	ata Nice Chi i B	
NOTICE OF IN	Appropriate Box to Indic		
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING			- A TO A WIND A DARK DOT WILLIAM
OTHER.	-	CASING TEST AND CE	MENT JOB
OTHER:	L	OTHER:	
12. Describe Proposed or Completed Oper	ations (Clearly state all pertinent detai	ls, and give pertinent dates, includ	ing estimated date of starting any proposed
1. Notify OCD of inten	t to plug	714	E COMMISSION MUST BE NOTIFIED 24
Z. M.I.R.W NU BOPE		CH	THE BEGINNING OF
3. Tag plug @6170' in '4. Pull the to 5800' s	'X" string, pump mud	to surface	AGGING OPERATIONS FOR THE C-103
		TO Surface TO	& APPROYED.
J. Pull tog to 434()' &	snot 10 gr omt		
O FULL LDG TO 1474' &	cnot 10 / /***	& tag) shoe plug	
			(HOC C +)
9. If top of plug is @1 10.R.I.H. w/CIBP on "#"	455'± P.O.H. & spot	Surface also for 201	(WUC & tag) shoe plug
10.R.I.H. w/CIBP on 'I'' 11.CIRC string to surfa	string & set @5875	W/5 SX Cement on to	to surface
11.CIRC string to surfa	ce w/mud	", o or cement on to	op
12. R.I. M. w/tbg to 580	0' & spot 10 see	nt	
13. I GIT LOS LO 4340. F	Shot In ex coment		
14. Pull the to 3420' a	Spot 10 sx cement (W	LO.C. & tag) shoe	plug
I hereby certify that the information above is that	e and complete to the best of my knowledge	and belief.	
SIGNATURE Lland n	1. leap	mue Engineer	DATE 4,2/98
TYPE OR PRINT NAME Dave	Deax		TELEPHONE NO.
(This space for State Use)			
ORIGINAL SIGN	VED BY		
APPROVED BY	1K		•
CONDITIONS OF ATTROVAL IF ANY:	. 1/	TITLE	DATE
CONTRACTOR OF PARTY OF ART 1			

NEW MCXICO "O" STATE (NCT-1) NO. 13 FIGURE 1

	x	15" NOLE TO 1550'. 114" 42" CSG SET AT 1550'. NUTH SOO SACAS CEMENT.
		IS 75' II" HOLE TO 3371'. 8 %" 24 " CSG SET NT 3374' WITH SOO SHOKS CEMENT. 3240'
TOP OF BLINEBRY PLUS AT 4170		GLORIETA PERFS: 5907-6131 PERFS TO COMMUNICATE GLORIETA WITH BLINEBRY STRINX;: 6115-6119
		BLINEBRY PENES: 6246-6477 (SQUETTED THE HOLF TO 6853', 2 STRINGS 2'6" 6.4 = CSG SET AT 6850' WITH 1200 SACKS CEMENT. T/CMT AT 3240 BY TEMP SURVEY 6818 PBTD

