Submit 3 Copies to Appropriate District Office	State of New Mer Energy, Minerals and Natural Res		Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hodde, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	I		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RES	ROPOSALS TO DRILL OF TO DEEPEN (ERVOIR. USE "APPLICATION FOR PER (C-101) FOR SUCH PROPOSALS.)	IMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well: Oll OAS WELL X WELL			Lovington 16 State
2. Name of Operator	OIL CORPORATION	<u></u>	8. Well No. 1
3. Address of Operator			9. Pool name or Wildcat
	BOX 5970 HOBBS, NM 882	41-5970	MIDWAY ABO
1.6	40 Feet From The North		0 Fret From The West Lit
		37E	
Section 16	Township 17S Ran 10. Elevation (Show whether D 3778	DF, RKB, RT, GR, etc.)	
11. Check	10. Elevation (Show whether L	DF, RKB, RT, GR, etc.) 3' RT Nature of Notice, R	
II. Check NOTICE OF IN	10. Elevation (Show whether L 3778 A Appropriate Box to Indicate N	DF, RKB, RT, GR, etc.) 3' RT Nature of Notice, R	eport, or Other Data
	10. Elevation (Show whether L 3778 Appropriate Box to Indicate N NTENTION TO:	DF, RKB, RT, GR, etc.) 3' RT Vature of Notice, R SUB	eport, or Other Data SEQUENT REPORT OF:
11. Check	10. Elevation (Show whether L 3778 Appropriate Box to Indicate N NTENTION TO: PLUG AND ABANDON	DF, RKB, RT, GR, etc.) 3' RT Vature of Notice, R SUB REMEDIAL WORK	eport, or Other Data SEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT

Oct. - Nov. 1991

RONN

Moved in Tyler Well Service & Bliss Pet. P & A equipment. Fished and LD rods. Pulled tubing. Ran CIBP @ 8890' w/ 2 sxs cement on top. 4 1/2" free above 5500'. Circulated hole w 10# gelled brine. Cut & pulled 5450' of 4 1/2" csg. Set 100' cement plug from 5500'-5400'. Perforated 2 holes @ 1405'. Establish circulation and pumped 150 sxs cement. Circulated 65 sxs to pits. Cut off well head. Install marker. Fig Down. Cut off anchors. Clean up location. Ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowled skonature	_ mr President & CEO	DATE5/06/92
YPE OR PRINT NAME Mohammed Yamin Merchant		тецерноме но. (505) 397-3
This space for State Use)		AUG 0 4 '92
APPROVED BY	- TMLE	DATE