NO. OF COPIES RE	CEIVED			Form C-103	
DISTRIBUT	ION			Supersedes Old C-102 and C-103	
SANTAFE		NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65	
FILE			$-\epsilon_{ij}$		
U.S.G.S.				5a. Indicate Type of Lease	
LAND OFFICE				State x Fee	
OPERATOR				S. State OH & Gas Lease No. State - B-155-1	
(DO NOT US	SUNDRY NOTICE SE THIS FORM FOR PROPOSALS TO DE USE "APPLICATION FOR PERM	ES AND REPORTS ON	WELLS ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)		
1. OIL X	GAS WELL OTHER-			7. Unit Agreement Name	
2. Name of Operato	r			8, Farm or Lease Name	
	TEXAC	O Inc.		St. of N. M. "O" NGT-1	
3. Address of Oper				9. Well No.	
	₽. 0.	. Box 728 - Hobbs	, Nev Mexico	20	
4. Location of Well			<del></del>	10. Field and Pool, or Wildcat	
UNIT LETTER _	B <u>167</u>	West	1980	Wacuum Blinebry West	
ONLY CELLER _	, , , , , , , , , , , , , , , , , , ,	EET FROM THE	CINE AND		
Lort Hort	A LINE, SECTION 36	10WHENTE 17-0	3h-E	NMPM.	
1,72	ZINC, SECTION	TOWNSHIP	AANGE	- · · · · · · · · · · · · · · · · · · ·	
		5. Elevation (Show whether		12. County	
		40161	(D. F.)	ī.sa ()	
16.	Check Appropria	te Box To Indicate N	ature of Notice, Report	t or Other Data	
	NOTICE OF INTENTION	I TO:	SUBSE	EQUENT REPORT OF:	
PERFORM REMEDIAL	WORK X	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABAN	DON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CAS	ING	CHANGE PLANS	CASING TEST AND CEMENT JQB		
		<del></del>	OTHER		
OTHER					
17. Describe Propo work) SEE RU	used or Completed Operations $(Cl)$	early state all pertinent det	ails, and give pertinent dates, i	including estimated date of starting any proposed	
∵le	propose to do the fo	ollowing work ca	subject well:		
1.	1. Pull Plinsbry & Glorieta pump equipment. Drill out cement from the Glorieta string from 5970' to 6600', in order to run a Gamma Ray Neutron log. Additional perforations are desired in the Blinsbry string as listed below, and to avoid perforating the Glorieta string a Radio-Active Pellet will be run in Glorieta string.				
2.	Perforate Blinebry string with one jet shot at 6406, 6415, 6427, 6444, 6459, 6483, 6509, 6518, 6547, 6556, and 6565. Acidize with 2200 gals 15% NE acid in 11 stages with one ball sealer between stages. Frac perforations with 20000 gals gelled lease crude with 20000 pounds of sand.				
3.	Swab well, recover				

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Assistant to the District DATE October 1, 1965

Superintendent

TITLE CONDITIONS OF APPROVAL, IF ANY: