

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002520143
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2706
7. Lease Name or Unit Agreement Name VACUUM GLORIETA WEST UNIT
8. Well No. 34
9. Pool name or Wildcat VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4014' RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	4. Well Location Unit Letter K : 1650 Feet From The SOUTH Line and 1650 Feet From The WEST Line Section 25 Township 17 S Range 34 E NMPM LEA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4014' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: ABANDON VACUUM BLINEBRY ZONE <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify NMOCD 24 hours prior to plugging operations.
- 2) MIRU Pulling Unit. Pull rods, pump and tubing.
- 3) Rig up Black Warrior (first-call supplier).
- 4) Run 4.343" gauge ring to 6380'.
- 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6375'.
- 6) Dump 35' of cement on top of CIBP (two dump bailer runs).
- 7) Run tubing, pump and rods. Return well to production.
- 8) Classify Vacuum Blinebry zone as plugged and abandoned. (Marathon McCallister #9)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Daniel A. Dunham TITLE PRODUCTION ENGINEER DATE SEPT 10, 1992
TYPE OR PRINT NAME DANIEL A. DUNHAM TELEPHONE NO. 397-0425

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

SEP 15 '92

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

VACUUM GLORIETA WEST UNIT 34
FORMERLY MCCALLISTER STATE #9
API# 30025201430000

"CURRENT WELLBORE DIAGRAM"

