

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Big "6" Drilling Company	8. Farm or Lease Name Hooper "B"
3. Address of Operator c/o Oil Reports & Gas Services, Inc. Box 763, Hobbs, NM 88241	9. Well No. 1
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM East THE LINE, SECTION 7 TOWNSHIP 19S RANGE 35E NMPM.	10. Field and Pool, or Wildcat Wildcat San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3884.7 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged for abandonment as follows:

Set cast iron bridge plug at 5500 & cap with 35' cement
Loaded hole with mud
Cut & pulled 4 1/2" casing from 4205
Ran tubing to 4255 & spot 80 sack cement plug
Tag top of plug at 3883.
Pull tubing up to 3300 and spot 30 sack cement plug
Perforate 4 holes at 1500 & set retainer at 1450
Squeeze 700 sacks cement thru perfs, maximum pressure 500#
Filled 8 5/8" - 13 3/8" annulus with cement
Set 10 sacks plug at surface with regulation marker
Well P & A 10/13/83

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wanda Hales TITLE Agent DATE 10/25/83

APPROVED BY Ronald M. [Signature] TITLE OIL & GAS INSPECTOR
CONDITIONS OF APPROVAL, IF ANY:

DATE APR 3 1984

RECEIVED
OCT 25 1983
HOBBS OFFICE