

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20148
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name VACUUM GLORIETA WEST UNIT
8. Well No. 32
9. Pool name or Wildcat VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Texaco Exploration and Production Inc.	
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	
4. Well Location Unit Letter <u>I</u> : <u>660</u> Feet From The <u>EAST</u> Line and <u>1780</u> Feet From The <u>SOUTH</u> Line Section <u>26</u> Township <u>17-S</u> Range <u>34-E</u> NMPM LEA	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4022' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ADD PAY AND ACIDIZE FORMATION ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. C/O TO 6433' (PBSD). PERF FR 6110'-6142' W/ 2 JSPF. (33 FT-66 HLES)
2. SPT 150 GALS 20% NEFE ACROSS PERFS, SET PKR @ 6030', SQZ AN ADDL 150 GALS 20% NEFE. SI 1 HR, SWAB BACK.
3. A/ PERFS FR 6110'-6142' W/ 3300 GALS 20% NEFE, MAX P = 4500#, AIR = 4 BPM. SWAB BACK, TEST ZONE.
4. TOH W/ PROD EQUIP. SET RBP @ 6050', SPT 6 BBL ACID FR 5900'-6050'.
5. PERF FR 5996'-6013' W/ 2 JSPF (18FT-36 HLES). SPT 84 GALS 20% NEFE ACROSS PERFS. SET PKR @ 5860', SQZ AN ADDL 84 GALS 20% NEFE. SI 1 HR & SWAB BACK. LOAD BS W/ FW.
6. A/ PERFS 5970'-6013' W/ 4500 GALS 20% NEFE, MAX P = 4500#, AIR = 4 BPM. SWAB BACK.
7. RETURN WELL TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 10-19-93

TYPE OR PRINT NAME MONTE C. DUNCAN

TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Paul Kautz TITLE Geologist DATE OCT 22 1993

CONDITIONS OF APPROVAL, IF ANY: