

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B2146	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name State V "B"
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 2
4. Location of Well UNIT LETTER K, 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 17S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 4009' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull rods, pump & tbq. Selectively perf. 5-1/2" csg. opposite Glorieta zone fr. 5978 6003', run pkr. & tbq. & acidize Glorieta zone thru 5-1/2" csg. perf. fr. 5930' to 6012' with 2000 gal. 15% NE acid using ball sealers as diverter. Swab test. Pull tbq. & pkr. Run drlg. bailer & knock bridge plug loose at 6100' & push down hole. Set CI bridge plug in 5-1/2" csg. at 6400'. Selectively perf. 5-1/2" csg. opposite Glorieta zone fr. 6067' to 6149'. Run pkr. & tbq., set pkr. at 6030' & acidize Glorieta zone thru 5-1/2" csg. perf. fr. 6067' to 6149' w/3000 gal. 15% NE acid using ball sealers as diverter. Swab test. Re-run tbq., pump & rods & resume production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. J. Fisher TITLE Supv. Adm. Ser. DATE 1-31-84

APPROVED BY _____ TITLE _____ DATE FEB 2 1984
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 1 1984

O.C.D.
MOBBS OFFICE