DISTRIBUTION	OIL CONSERVATION DIVISION	Form C-103
SANTA FE		
	SANTA FE, NEW MEXICO 87501	
FILE	1 - 1 - 7 - 1 - 7 - 1 -	Sa. Indicate Type of Lesse
1.5.0.3.	2-Midland 1-Engr. LM	State X Foo
LAND OFFICE	I-ForemanEF	5. State Oli & Gas Lease No.
OPERATOR	C T A 1920 COMBERT TO AND AND A COMPANY AND	B-1565
DO NOT USE THIS FORM FOR PROPOSALS TO USE "APPLICATION FOR PER	CES AND REPORTS ON WELLS	7. Unit Agreement Name
Name of Operator		8. Farm or Lease Name
ETTY OIL COMPANY		State BA
Address of Operator		9. Well No. 5
.O. BOX 730, Hobbs, New Mexic	co 88240	
Location of Well		10. Field and Pool, or Wildcat
	FEET FROM THE N. LINE AND 560	Vac: Blinebry-Gloriet
UNIT LETTER 0000	_ FEET FROM THEEINE ANDEINE AND	
KNV 36	5TOWNSHIPRANGE34E	
THE LINE, SECTION	TOWNSHIP RANGE TOWNSHIP	HMPM. ())))))))))))))))))))))))))))))))))))
mmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4018' DF	Lea
	iate Box To Indicate Nature of Notice, Rep	ort or Other Data
NOTICE OF INTENTIO	ON TO: SUB	SEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT J	lga
	OTHER	
Additionally perforat	te, acidize X	
7 Ceacritice Proposed or Completed Operations	(Clearly state all pertinent details, and give pertinent date	es, including estimated date of starting any proj
work) SEE RULE 1103.		
		/- //
	a dual, tubingless completion. The	
orated in the Glorieta from 5	5951'-6118'. The 2-7/8" east casing	is perforated in the
linebry from 6367'-6644'. Ge	etty proposes to additionally perf t	he Glorieta in the west
-	ta and Blinebry zones. To provide a	
	as locking, Getty also proposes to d	
	roval of the NMOCD in Santa Fe. A h	earing has been requested.
. Pull rods and pump from we	est string.	
• Full rous and pump from we	5' PBTD.	
± •		
. Clean out with bit to 6696	-he Glorieta at 5842! 43! 54! 55! 64	
Clean out with bit to 6696Perforate west string in t	the Glorieta at 5842',43',54',55',64	
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 	25',50',52',53',oriented away from e	
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with 	25',50',52',53',oriented away from e n bit to 6696' PBTD.	ast string.
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac 	25',50',52',53',oriented away from e n bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi	ast string. th 5000 gals. 15% NE.
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac 	25',50',52',53',oriented away from e n bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi	ast string. th 5000 gals. 15% NE.
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Via 2-7/8" east casing, ac 	25',50',52',53',oriented away from e h bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi	ast string. th 5000 gals. 15% NE.
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Via 2-7/8" east casing, ac Set 2-7/8" RBP in east str 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'.	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE.
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Via 2-7/8" east casing, ac Set 2-7/8" RBP in east string Perforate the west string 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Set 2-7/8" RBP in east string Perforate the west string 6250'. 2-3 perfs will hit 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at t east string in each case, downhole	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Via 2-7/8" east casing, ac Set 2-7/8" RBP in east string Perforate the west string 6250'. 2-3 perfs will hit Run rods and pump in east 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Via 2-7/8" RBP in east string Set 2-7/8" RBP in east string Perforate the west string 6250'. 2-3 perfs will hit 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Set 2-7/8" RBP in east string Set 2-7/8" RBP in east string 6250'. 2-3 perfs will hit Run rods and pump in east string will be used to flo 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu ow gas.	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings and to production. West
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Via 2-7/8" east casing, ac Set 2-7/8" RBP in east string Perforate the west string 6250'. 2-3 perfs will hit Run rods and pump in east string will be used to flo 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings and to production. West
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Set 2-7/8" RBP in east string 6250'. 2-3 perfs will hit Run rods and pump in east string will be used to flo 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu bw gas.	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings in to production. West
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Set 2-7/8" RBP in east string 6250'. 2-3 perfs will hit Run rods and pump in east string will be used to flo 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. .with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu ow gas.	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings in to production. West
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Set 2-7/8" RBP in east string 6250'. 2-3 perfs will hit Run rods and pump in east string will be used to flo 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu bw gas.	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings inn to production. West ent
 Clean out with bit to 6696 Perforate west string in t 35'88',89',6010',11',22',2 Clean out east string with Via 2-7/8" west casing, ac Set 2-7/8" RBP in east string 6250'. 2-3 perfs will hit Run rods and pump in east string will be used to flo 	25',50',52',53',oriented away from en bit to 6696' PBTD. cidize Glorieta perfs 5842'-6118' wi cidize Blinebry perfs 6367'-6644' wi ring at 6330'. with 10 shots using a spiral gun at t east string in each case, downhole string, set pump at 6225', and retu bw gas. • true and complete to the beat of my knowledge and belief	ast string. th 5000 gals. 15% NE. th 4000 gals. 15% NE. 6367' and 10 shots at commingling the two strings in to production. West

APPILOVED				
C 014 DI TI	ONSOF	, PISIBICI	I.SURFRVI	SOR

