Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

CALL PLOT I VIEL HONDA NILL XE/ALL	M 88240 OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	
DISTRICT III P.O. Drawer DD, Artesia, NM \$8210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		30-025-20720		
		5. Indicate Type of Lease STATE X FEE		
		6. State Oil & Gas Lesse No. A-1320		
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name		
				1. Type of Well: OH WELL X WELL OTHER
2. Name of Operator Phillips Petroleum Company		8. Well No. 1		
3. Address of Operator 4001 Penbrook St. Odessa, TX 79762		9. Pool name or Wildcat Vacuum Glorieta		
4. Well Location			leta	
Unit Letter B 330 Feet From The North	Line and2306	Feet From Th	e Line	
Section 32 Township 17S		NMPM Lea	County	
10. Elevation (Show w) 3964 'GI	hether DF, RKB, RT, GR, etc.)			
11. Check Appropriate Box to Indic	ate Nature of Notice, R	eport or Other D	//////////////////////////////////////	
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF		
JLL OR ALTER CASING CASING TEST AND CE		<b></b>		
OTHER:		· · · · · · · · · · · · · · · · · · ·		
12. Describe Proposed or Completed Operations (Clearly state all pertinent detwork) SEE RULE 1103.	ails, and give pertinent dates, inclu	ding estimated date of sta	rting any proposed	
<ol> <li>MIRU. POOH w/rods.</li> <li>NU Class 2 BOPE.</li> <li>POOH w/2-3/8" production tubing.</li> <li>GIH and perf. 4 squeeze holes at</li> <li>GIH with RBP and packer on 2-3/8" test RBP to 500 psig. Spot 2 sxs</li> <li>Hold 500 psig on annulus during i Establish injection rate and pres casing valves.</li> <li>Squeeze method and cement slurry on pump in rates and pressures.</li> <li>COOH with tubing.</li> </ol>	production tubi sand on top of R njection into sq sure and attempt	ng. Set pkr BP. ueeze perfor circulation	ations. out surface	
I hereby certify that the information above is true and complete to the best of my knowled	ige and belief.			
SIGNATURE Marco	_ mu Supv. Regul	atory Affair	B 04-05-94	
TYPE OR PRENT NAME L. M. Sanders			(915) TELEFHONE NO. 368-1488	
(This space for State Use)	ORIGINAL SIGNED DISTRICT I	BY JERRY SEXTON	MAY 0 3 1994	
APPROVED BY			DATE	
CONDITIONS OF AFFROVAL, IF ANY:		••••		

Vacuum Glorieta East Unit Tract 2 Well No. 1 Vacuum Glorieta API No. 30-025-20720 Lease No. A-1320 Lea County, NM Form: C-103

- 9. GIH wit 3-7/8" bit and drill collars on 2-3/8" tubing. Drill out cement. Pressure test squeeze perforations and casing to 500 psig. Monitor surface casing valves to insure no pressure. Tag sand and RBP at 3000' and circulate hole clean. POOH.
- 10. Wash sand off of RBP and retrieve. Go downhole with RBP and set at +/-5900'. Pressure test 4-1/2" production casing to 500 psig and record on circular chart. Tag and record PBTD, and POOH with RBP.
- 11. GIH with 2-3/8" tubing, placing seating nipple to at least depth of bottom perf at 6176'.
- 12. Place well back on production.

05-03-94 AF:ehg RegPro:AFran:VGEUT2W1.103

PECEVED

OFFICE