

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-20862
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520-1
7. Lease Name or Unit Agreement Name STATE DD COM
8. Well No. 1
9. Pool name or Wildcat WOLFCAMP/PENN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator MOBIL PRODUCING TX & NM INC.* *MOBIL EXPLORATION & PRODUCING US INC. AS AGENT FOR MPTM	
3. Address of Operator P.O. Box 633 Midland, TX 79702	
4. Well Location Unit Letter D : 510 Feet From The NORTH Line and 535 Feet From The WEST Line Section 31 Township 17S Range 35E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3987' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU PLUGGING UNIT.
2. POH & LD PRODUCTION EQUIPMENT
3. RU WL & SET 7" RETAINER @ 9200.
4. RIH W/STINGER & WORKSTRING TO RETAINER & SQUEEZE W/150 SXS CMT BELOW/CAP W/25 SXS.
5. CIRCULATE HOLE W/95# SALT GEL.
6. PULL TBG TO 7500'. SPOT 25 SXS CMT., (7500-7400') TOC/TAG. POOH W/TBG.
7. SPOT 40 SXS 5050-4950' (SHOE & STUB PLUG) WOC & TAG.
8. SPOT 45 SXS 2700-2600' (BOTTOM SALT)
9. SPOT 45 SXS 1550-1450' (SALT TOP)
10. SPOT 10 SXS @ SURFACE 15-3'.
11. INSTALL DRY HOLE MARKER/CLEAN LOCATION/RECLAMATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Houchins for TITLE ENV & REG TECHNICIAN DATE 3-22-99
TYPE OR PRINT NAME SHIRLEY HOUCHINS TELEPHONE NO. 915 688-2585

(This space for State Use)

FOR RECORD ONLY

APPROVED BY _____ TITLE _____ DATE JUN 28 1999
CONDITIONS OF APPROVAL, IF ANY: _____