Submit 3 Copies to Appropriate District Office

APPROVED BY...

CONDITIONS OF APPROVAL IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Drawn I am I				Revised March 25, 1999
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 DISTRICT II 811 South First, Artesia NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV 2040 South Pacheco, Sante Fe, NM 87505			WELL API NO. 30-025-21363	
			5. Indicate Type of Le	state 🛛 FEE
			6. State Oil & Gas Lease No. B-1520	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)				
			7. Lease Name or Unit Agreement Name Bridges State	
1. Type of Well:	Geo. —			
Oil Well	Gas Well Other Inject	or	8. Well No.	
2. Name of Operator Exxon Mobil Corporation			105	
3. Address of Operator P.O. Box 435 Houston	58 TX 772	210-4358	9. Pool name or Wild Vacuum; Graybu	
4. Well Location	0 N41	500	T .	
Unit Letter : 660	Feet From The North	Line and 500	Feet From The East	Line
Section 26	Township 17S	Range 34E	NMPH	Lea County
	10. Elevation (Show whethe GR 4010'	TDR, KKB, KI, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
			BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	. –	REMEDIAL WORK		LTERING CASING L
TEMPORARILY ABANDON		COMMENCE DRILLI		LUG & ABANDONMENT L
PULL OR ALTER CASING L	MULTIPLE COMPLETION	CASING TEST AND O	CEMENT JOB L	
OTHER:		OTHER:		
12. Describe proposed or completed o work) SEE RULE 1103. (For Mo	operations. (Clearly state all pertinent ultiple Completions: Attach wellbore	diagram of proposed comp	letion or recompletion)	ted date of starting any propose
1. Move in and rig up well service unit. Kill well as needed.			GGING OPERATIONS FOR THE 13493	
2. Rig up BOP equipment. 3. Unseat packer and POH with tubing.			SE APPROVED.	
4. Rig up wireline unit and go in hole with CIBP and set at 4280', which is within 100' of the perforated hole zone. Dump bail				
no less than 35' of cement on top of plug. POH and rig down wireline unit. 5. Run in hole with tubing string to TOC. Circulate packer fluid				
6. POH and lay down tubing leaving 1000' of kill string in wellbore.				
	'est by pressuring the casing to	500 psi for no less than	30 minutes	
to demonstrate good casing int 8. RDMO.	egrity.			
V				
I hereby certify that the information above is true and com	• \		£ 25.0	
SIGNATURE (). How		Regulatory Specialist	# 2919	DATE 11/30/2000
TYPE OR PRINT NAME Dolores O. Howard TELEPHONE NO. (713) 431-1792				
(This space for State Use)			Salar Salar	