

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-9512

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name None
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name New Mexico 'CW' St.
3. Address of Operator P.O. Box 728 - Hobbs, New Mexico 88240	9. Well No. NCT-1 1
4. Location of Well UNIT LETTER K 1983 FEET FROM THE South LINE AND 1906 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 17-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Midway Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3810' (D.F.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TEXACO HAS COMPLETED THE FOLLOWING WORK ON SUBJECT WELL:

1. Ran 2-3/8" O.D. tubing and mud up hole.
2. Spot 15 sx cement plug on top of stuck 2-3/8" O.D. tubing from 4271' to 4111'.
3. Cut off 4-1/2" O.D. casing @ 4205' and pulled same.
4. Spot 40 sx. cement plug 4260' - 4090'.
5. Spot 30 sx. cement plug 3255' - 3155'.
6. Spot 15 sx. cement plug 40' - 0'.
7. Set 4" dry hole marker extending 4' above ground level and clean up location for inspection.

REQUEST THAT THE ALLOWABLE FOR SUBJECT WELL BE SET AT ZERO (0).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. M. Myers TITLE Assistant District Superintendent DATE February 13, 1969

APPROVED BY John W. Runyan TITLE Geologist DATE JUL 23 1969

CONDITION OF APPROVAL, IF ANY: