

## NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name C. M. Selby	
9. Well No. 1	
10. Field and Pool, or Wildcat Midway Abo	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Atlantic Richfield Company

3. Address of Operator

P. O. Box 1710, Hobbs, New Mexico 88240

4. Location of Well

UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM  
THE East LINE, SECTION 18 TOWNSHIP 17S RANGE 37E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

3813' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐PLUG AND ABANDON ☒CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOBS ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 9020', PBD 9001'. Present Perfs 8965-8990' w/10 - 3/8" holes.

13-3/8" OD csg set @ 352' &amp; cmt circulated.

8-5/8" OD csg set @ 4800' &amp; cmt w/2700 sx. Cmt circulated.

4-1/2" OD csg set @ 9020' (4 1/2" OD csg pulled from 5419').

2-7/8" OD tbg for csg set @ 8912' &amp; cmt from 4900'-8912'.

Propose to plug &amp; abandon in the following manner:

1. Rig up, install BOPs &amp; POH w/rods &amp; pump.

2. Displace 70 sx Class C cmt cont'g 4% gel w/wiper plug to 5400'.

3. Run free pt &amp; cut off 2-7/8" &amp; pull. Fill hole w/9# mud.

4. Spot 30 sk cmt plug across 8-5/8" csg shoe @ 4800'.

5. Spot 30 sk cmt plug 2100-2200' across top of salt @ 2165'.

6. Remove csg hd &amp; spot 10 sk cmt plug @ surface, install regulation dry hole marker, clean &amp; level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED

Dist. Drlg. Supv.

4/24/75

Orig. Supv.

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: