Submit 3 Copies to Appropriate
District Office

State of New Mexico Energy, N....erals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

DISTRICTION (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF DEEPEN OR PLUG BACK TO A DISTRICTION OF PROPOSALS TO DRILL OF DEEPEN OR PLUG BACK TO A DISTRICTION OF PROPOSALS.) 1. Type of Well: Common Charles Charles Common Charles	DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well.	PAGE TO STATE AND STATE AND A	6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPER OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Wal: 1. Type of Wal: 1. Name of Openior 2. Well No. 1. Pool name of Wildrat 1. Emerald Abo 1. Well Loatoo 1. Well Loatoo 1. Well Loatoo 1. The Section of The West		E-5766	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPER OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Wal: 1. Type of Wal: 1. Name of Openior 2. Well No. 1. Pool name of Wildrat 1. Emerald Abo 1. Well Loatoo 1. Well Loatoo 1. Well Loatoo 1. The Section of The West	SUNDRY NOTICES AND REPORTS ON WELLS		
Type of Well: ONL Well OTHER	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name	
A detect State			
2. Name of Operator Elk Oil Company 3. Address of Operator Post Office Box 310, Roswell, New Mexico 4. Well Locator Usis Lester W : 660 Feet From The West Lise and 660 Feet From The South Line Section 15 Township 17 South Range 36 East NMPM Lea County 10. Elevation (Shorw whether DF, RKB, RT, GR, stc.) 3850' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	OT GAS	Aztec State	
Notices of Operator Post Office Box 310, Roswell, New Mexico S. Poot tasine or Wildest Emerald Abo		8. Well No.	
Post Office Box 310, Roswell, New Mexico Well Location Unit Letter M : 660 Feet From The West Line and 660 Feet From The South Line Section 15 Township 17 South Range 36 East NMFM Lea County 3850' GR 16. Elevation (Show whether DF, RKB, RT, GR, etc.) 3850' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CASING TEST AND CEMENT XOB OTHER: OT	Elk Oil Company	1	
Well Location Unix Letter M: 660 Feet From The West Lise and 660 Feet From The South Line Section 15 Township 17 South Range 36 East NMFM Lea County 10. Elevation (Shore whether DF, RKB, RT, GR, etc.) 3850' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertisent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Proposed plug and abandonment plan as follows: (1) Set Cast Iron BP @ 9400' with 35' coment cap. (2) Cut 5% casing @ 7500 **, recover pipe. (3) Place 30 sx plug in and out of 5% plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing, top of Salt @ 2160'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Place mud between all plugs. The President DATE DATE TOWNS IN THE PRESIDENT. THE President DATE TOWNS IN THE DATE TOWNS IN THE PRESIDENT. THE President DATE TOWNS IN THE BOUND IN THE DATE TOWNS IN THE BOUND IN THE DATE TOWNS IN THE DATE TOWNS IN THE DATE TOWNS IN THE BOUND IN THE BOUND IN THE DATE TOWNS IN THE BOUND IN TH	3. Address of Operator		
Unit Letter M: 660 Feet From The West Line and 660 Feet From The South Line Section 15 Township 17 South Range 36 East NMFM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3850' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CHANGE PRILLING OPNS. PLUG AND ABANDONMENT CHANGE PLANS C		Emerald Abo	
10 10 10 10 10 10 10 10	M 660 p p West lineard	660 Feet From The South Line	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3850' GR 3850' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB DTHER: OTHER: OTHE	Section 1 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3850' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 110 Proposed plug and abandonment plan as follows: (1) Set Cast Iron BP @ 9400' with 35' cement cap. (2) Cut 5% casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5% plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stub @ 1000'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Place mud between all plugs. Inc. President DATE DATE 12/19/90			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 Proposed plug and abandonment plan as follows: (1) Set Cast Iron BP @ 9400' with 35' cement cap. (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stub @ 1000'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location **Policy of the Complete to the best of my knowledge and belief. **TILE President DATE 12/19/90			
REMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER:		BSEQUENT REPORT OF:	
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103 Proposed plug and abandonment plan as follows: (1) Set Cast Iron BP @ 9400' with 35' cement cap. (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stub @ 1000'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Place MILLING OPNS. Place mud between all plugs. 1 herrory certly that the upformation above us true and complete to the best of my knowledge and belief. SUNATURE TILLE President PATE 12/19/90		ALTERING CASING	
CASING TEST AND CEMENT JOB OTHER: OT		NG OPNS. PLUG AND ABANDONMENT	
OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1100 Proposed plug and abandonment plan as follows: (1) Set Cast Iron BP @ 9400' with 35' cement cap. (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stub @ 1000'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Description Place Description Descriptio		CEMENT JOB	
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including entimated date of starting any proposed work) SEE RULE 1103 Proposed plug and abandonment plan as follows: (1) Set Cast Iron BP @ 9400' with 35' cement cap. (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stub @ 1000'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Post Pace Pace Pace Pace Pace Pace Pace			
(1) Set Cast Iron BP @ 9400' with 35' cement cap. (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500'. (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ 2160'. (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stub @ 1000'. (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Description Place Pl	OTHER:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signature President Date 12/19/90		riviine eximated date of starting any proposed	
SIGNATURE President DATE 12/19/90	(1) Set Cast Iron BP @ 9400' with 35' cement cap (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500' (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stu (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location	2160'. b @ 1000'.	
SIGNATURE TITLE TAGGETT	(1) Set Cast Iron BP @ 9400' with 35' cement cap (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500' (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stu (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Decomplete of the Ross of the end of the plugs.	2160'. b @ 1000'.	
SIGNATURE	(1) Set Cast Iron BP @ 9400' with 35' cement cap (2) Cut 5½ casing @ 7500 +, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500' (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stu (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Decomplete of the Ross of the end of the plugs.	2160'. 2b @ 1000'.	
	(1) Set Cast Iron BP @ 9400' with 35' cement cap (2) Cut 5½ casing @ 7500 ±, recover pipe. (3) Place 30 sx plug in and out of 5½ plug @ 7500' (4) Place 50 sx plug at base of 8 5/8 casing 4400'. (5) Place 100' plug in 8 5/8 casing, top of Salt @ (6) Cut 8 5/8 casing @ 1000', recover pipe. (7) Place 50 sx plug in and out of 8 5/8 casing stu (8) 10 sx plug @ surface. (9) Place 4' X 4' dry hole marker. (10) Level and clean location Description Place Presiden Pr	2160'. b @ 1000'.	

(This space for State Use)

APPROVED BY --