SANTA FE SANTA FE SLATA	NO. OF COPIES RECEIVED]	Form C-103
NEW MEXICO OIL CONSERVATION COMMISSION File	DISTRIBUTION] HOBBS LIFTCE $0, \mathbf{C}, \mathbf{C}, \ldots$	•
DEFRATOR SUNDRY NOTICES AND REPORTS ON WELLS Subject of a date Leave No. Oct 1049	SANTA FE		
DEFRATOR SUNDRY NOTICES AND REPORTS ON WELLS Subject of a date Leave No. Oct 1049	FILE	☐ FEB 15 II so AM '67	
S. State CIT & Down Lower No. OG 10.49 Sunday Sunday	U.S.G.S.		
SUNDRY NOTICES AND REPORTS ON WELLS Commence Comme	LAND OFFICE		
SUNDRY NOTICES AND REPORTS ON WELLS COLUMN TO THE THIS FOREIGN TO THE THIS THE THIS THE THIS THE THIS THIS THE THIS THE THIS THE THIS THE THIS THIS THE THIS THE THIS THIS THE THIS THIS THIS THIS THE THIS THIS THIS THIS THIS THIS THIS THIS	OPERATOR		5. State Oll & Gas Lease No.
The state of Complete Conspired Constitution of Canal Plans Canal Plan			OG 1049
1. Name of Coperator ELK OIL COMPANY 3. Address of Coperator BOX 310, ROSWell, New Mexico 4. Location of Well Unit Letter L South THE SOUTH LINE, SECTION 15 TOWNSHIP 175 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUS AND ASSAUDON THENDRALLY ASSAUDON THE SAME PLANS OTHER A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ 9400 Aboo 25 sx @ 9500 Tubb 25 sx @ 5000 base SA 25 sx @ 5200 top SA 25 sx @ 5700 Tubb 25 sx & 58 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	SUNDRY NOTICES AND REPORTS ON WELLS		
TELK OIL COMPANY 3. Address of Operation BOX 310, Roswell, New Mexico 4. Location of Weil DUIL LITTER L 660 SOUTH THE Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PAUS AND ABANDON TELFORMATIVE ARANDON PULL OF ALTER CASING CHARGE PLANS CHARGE PLANS OTHER AT TO of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ 400 Abo 25 sx @ 9400 Abo 25 sx @ 6000 Tubb 25 sx @ 6000 Tubb 25 sx @ 6000 Tubb 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	OIL GAS		7. Unit Agreement Name
3. Address of Convenior Box 310, Roswell, New Mexico 4. Lecation of Well Unit Lettes South Int. section 15 Tomaship 175 Tomaship 175 Tomaship To	1		
Box 310, Roswell, New Mexico 4. Location of Well Unit Lettes South Line, Section 15 Township 17: South Line, Section 15 Township 17: Sarage 36E Number 12. County 12. County Lea 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUS AND ABANDON AACTOR ACTOR WILL ON ALLT TO FIRM THE AND TO FIR			
UNIT LETTER L 660 THE SOUTH 15 TOWNSHIP 17S NAME 36E NAPM 15. Elevation (Show whether DF, RT, GR, etc.) 3848 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ***PLUS AND ARABODO NOTICE OF INTENTION TO: ***PLU			
South Line, section 15 rownship 178 have 36E support or Other Data 3848 GL Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: **Representative of Notice of Indicate Nature of Notice of Notice of Indicate Nature of Other of Indicate Nature of Notice of Indicate Nature of Other of Other of Indicate Nature of Other of O			10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3848 GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPRAMILY NAMADON PULL OR ALTER CASING OTHER OTHER A TTO of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6900 Tubb 25 sx @ 6900 Tubb 25 sx @ 6000 base SA 25 sx @ 5200 top SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 § fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of sait - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	UNIT LETTER	660 FEET FROM THE West LINE AND 1980 FEET FR	Wildcat
TEMPORALITY ASARDON A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 base sA 25 sx @ 6000 base sA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.		15 TOWNSHIP 17S RANGE 36E	
TEMPORALITY ASADON A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 base SA 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORANIEV ASANDON THE OF ALTER CASING OTHER OTHER A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6900 Tubb 25 sx @ 6000 base SA 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx was end for approval to plug and restored to the original contour.			Lea
NOTICE OF INTENTION TO: PLUG AND ABANDON PULL OR ALTER CABING PLUG AND ABANDON PULL OR ALTER CABING PLUG AND ABANDONMENT CHANGE PLANS CASING TEST AND GEMENT JGB PLUG AND ABANDONMENT CHANGE PLANS	16, Ch - ale		Oal as Dana
TEMPORABILY ARANDON PULL OR ALTER CASING CHANGE PLANS CHANGE PLANS COMMENCE ORBILLING COMB. OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see Nulle'1768. A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6900 Tubb 25 sx @ 6900 base SA 25 sx @ 5200 top SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.			
A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 Tubb 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx û a 400 base of sold sub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE NULE 1703. A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6900 Tubb 25 sx @ 6000 base SA 25 sx @ 5200 top SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE'1703. A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 Tubb 25 sx @ 6000 base SA 25 sx @ 5200 top SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see NOLE 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 base SA 25 sx @ 6000 base SA 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.		OTHER	
A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 base SA 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	OTHER		
A TD of 10,100 was reached on 2-8-67 after DST's failed to prove any oil or gas production on 2-11-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows: 25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6000 base SA 25 sx @ 6000 base SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	10 Death Break a Control (Charle see all partners destined the parties of the budge estimated date of starting any proposed		
25 sx @ TD 10,100 25 sx @ 9400 Abo 25 sx @ 6900 Tubb 25 sx @ 6000 base SA 25 sx @ 5200 top SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	A TD of 10,100 any oil or gas	was reached on 2-8-67 after DST's failed production on 2-11-67 we asked for approximately approximately asked for approximately	ed to prove roval to plug
25 sx @ 9400 Abo 25 sx @ 6900 Tubb 25 sx @ 6000 base SA 25 sx @ 5200 top SA 25 sx @ 4400 base of 8 5/8 shoot off free 8 5/8 & fill annulus w/mud 25 sx in 8 5/8 stub; 25 sx top of salt - 2100 25 sx base of surface - 350; 10 sx @ surface w/4'x4" marker Location will be cleaned up and restored to the original contour.	in addition. To prain to prace comone prago as torrows.		
SIGNED / LU MILLE Agent DATE 2-13-67	25 sx @ 940 25 sx @ 690 25 sx @ 600 25 sx @ 520 25 sx @ 440 shoot off f 25 sx in 8 25 sx base	00 Abo 00 Tubb 00 base SA 00 top SA 00 base of 8 5/8 00 base of 8 fill annulus w/mud 5/8 stub; 25 sx top of salt - 2100 of surface - 350; 10 sx @ surface w/4'x	c4" marker riginal contour.
SIGNED / LU MILLE Agent DATE 2-13-67	19 I heraby cartify that the information	n shower to true and complete to the heat of my knowledge and helief	
	/ 1	a door of the complete to the best of my knowledge and belief.	
	V. IV. IM	Agent Agent	DATE 2-13-67
	SIGNED		

COND. TIONS OF APPROVAL, IF ANYI