

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 1 3 02 PM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	State - K-5386

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name NONE
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name N. M. "DL" State NCT-1
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>17-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3870' (D. F.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well has been plugged & abandoned as follows:

1. Spot 40 Sx. cement plug from 9250' to 9350'.
2. Spot 40 Sx. cement plug from 7600' to 7700'.
3. Spot 40 Sx. cement plug from 6750' to 6850'.
4. Spot 40 Sx. cement plug from 5200' to 5300'.
5. Spot 40 Sx. cement plug from 4450' to 4550'.
6. Spot 40 Sx. cement plug at casing stub (8 5/8"), from 1650' to 1750'.
7. Spot 40 Sx. cement plug from 300' to 400'.
8. Spot 20 Sx. surface plug, 0' to 40', install 4" marker extending 4' above ground level, clean the location for inspection by the New Mexico Oil Conservation Commission, Plug and abandon complete July 29, 1967.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. E. Morgan</u>	TITLE <u>Assistant District Supt.</u>	DATE <u>August 1, 1967</u>
APPROVED BY <u>John W. Ryan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		