

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
St. Clair Energy Corporation
3. ADDRESS OF OPERATOR
501 First Nat'l Bank Bldg., Midland, Tx 79701
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
Unit 1, 1980' FSL & 660'
AT SURFACE: FEL Sec. 25, T-19-S,
AT TOP PROD. INTERVAL: R-34-E
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: | SEQUENT REPORT OF: |
|---|-------------------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| (other) <input type="checkbox"/> | <input type="checkbox"/> |

5. LEASE
29-000086
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Superior Federal
9. WELL NO.
87
10. FIELD OR WILDCAT NAME
Pearl Seven Rivers
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 25, T-19-S, R-34-E
12. COUNTY OR PARISH
Lea
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3762 KDB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 5150

PBTD 4218

- 1) Set 25 Sx Bottom plug over perf 3967-4075'
- 2) Set 25 Sx plug @ 2100' in 5 1/2 casing. Base salt.
- 3) Shot 5 1/2 casing @ 1750' & pulled out.
- 4) Set 35 Sx plug @ 1750' - Top salt.
- 5) Tag plug @ 1600'
- 6) Set 40 Sx plug @ 267' Bottom of 8 5/8" surface casing
- 7) Set 10 Sx plug @ surface 5-6-83
- 8) Weld cap on casing
- 9) Place well marker
- 10) Well site ready for final inspection
Cement applied by pump.
Well filled with mud-laden fluid by pump.



Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED George A. Hume TITLE Agent DATE July 21, 1983

(This space for Federal or State office use)

APPROVED BY Don W. [Signature] TITLE _____ DATE 3-15-85

CONDITIONS OF APPROVAL, IF ANY: