

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-23093</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. OG-2416
7. Lease Name or Unit Agreement Name Hooper "B"
8. Well No. 1
9. Pool name or Wildcat Quail Queen

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Read & Stevens, Inc.	
3. Address of Operator P. O. Box 1518 Roswell, NM 88202	
4. Well Location Unit Letter <u>M</u> : <u>801.4</u> Feet From The <u>S</u> Line and <u>791.17</u> Feet From The <u>W</u> Line Section <u>7</u> Township <u>19S</u> Range <u>35E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3933.8 GL	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Read & Stevens, Inc. proposes to P&A this well as follows:

- 1) Set CIBP w/2 sx cmt on top, or 100' cmt plug above the top perf @ 5,018' and tag plug.
- 2) Circ well w/ 9ppg mud laden fluid.
- 3) Cut and pull 4 1/2" csg from 4,000', set 100' cmt plug in 8 5/8" shoe @ 4,000' and tag.
- 4) Set 100' cmt plug @ top of salt @ 2,000' and tag.
- 5) Free point and shoot 8 5/8" csg, pull 8 5/8" csg.
- 6) Set 100' cmt plug @ 8 5/8" stub and tag.
- 7) Set surf plug and install DHM. Clean location.

100' PLUG ABOVE 12 3/4 SHOE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Maxey, Jr. TITLE Petroleum Engineer DATE 3-26-92  
TYPE OR PRINT NAME John C. Maxey, Jr. TELEPHONE NO. 505/622-3770

(This space for State Use)

ORIGINAL SIGNED BY JERRY LINTON

APPROVED BY DAVID L. LINTON TITLE Assistant Secretary DATE APR 06 '92

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION SHALL BE NOTIFIED 24 HOURS BEFORE THE BEGINNING OF PROPOSED OPERATIONS FOR THE C-103 TO BE APPROVED.