

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SALE TAX	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR REGULATE TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR TO REOPEN OR REGULATE FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
6. Name of Operator Mobil Producing TX. & N.M. Inc.		5. State Oil & Gas Lease No. B-1520
7. Unit Agreement Name		8. Farm or Lease Name North Vacuum Abo Unit
9. Well No. 156		
10. Field and Pool, or Wildcat North Vacuum Abo		12. County Lea
11. Elevation (Show whether DF, RT, GR, etc.) 4013 GR		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☒ TEMPORARILY ABANDON ☐ NULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐
REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- POOH w/rods, pump and tubing.
- GIH w/RBP and set at 2700, cap with sand.
- GIH w/cmt bond log and locate the top of the cement, estimated at 2610 (from temperature survey).
- GIH w/perforating gun and perforate w/6 shots at the top of the cement.
- Bleed down any pressure, then GIH w/cmt retainer, set 50' above perms.
- Establish circulation behind 5½ casing to surface by pumping a fluid caliper (dye) w/water.
- Cement well w/800 sx of Class "C" w/2% calcium chloride, circulate to surface and squeeze to 300 psi.
- POOH and determine if cement set.
- If cement did not circulate run a temperature survey to find the top of the cement and evaluate.
- GIH and drill out cement plug.
- Pressure test to 1000 psi, do not exceed 1000 psi.
- Circulate sand off of RBP and retrieve RBP.
- GIH w/rods, pump and tubing.
- Space the pump and return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ronnie Jay</u> Orig. Signed by Jerry Sexton	TITLE <u>Authorized Agent</u>	DATE <u>4/11/80</u>
MOVED BY <u>Dist. 1, Sup.</u>	TITLE	DATE <u>APR 11 1980</u>

CONDITIONS OF APPROVAL, IF ANY: