

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.

L1115

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Oil & Gas Corp.	8. Farm or Lease Name Scharb #2" State
3. Address of Operator 900 Wilco Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER M, 660 FEET FROM THE west LINE AND 660 FEET FROM THE South LINE, SECTION 2, TOWNSHIP 19-S, RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Scharb (Bone Spring)
15. Elevation (Show whether DF, RT, GR, etc.) 3995' KB	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/19/76 Set CIBP at 10450 /w 35 sacks cement on top

8/20/76 Load Hole w/ 10 lb mud

8/21/76 thru 23/76 Cut 5½ Casing at 9545 and pull

8/25/76 Set cement plug w/tubing, 30 sacks at 9576, 40 sacks at 7056, 40 sacks at 5323, 45 sacks at 4126.

8/26/76 Cut 8 5/8 at 550 and pull. Set 30 sacks at 1955, 75 sacks at 567. 40 sacks 420, 10 sacks at top. Weld plate over 13 3/8 and place monument, well P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Galt TITLE Staff Engineer DATE August 31, 1976

APPROVED BY John W. Runyan TITLE  DATE JAC

CONDITIONS OF APPROVAL, IF ANY: