

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API No. 30-025-26526

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2131	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name East Vacuum Gb/SA Unit
2. Name of Operator Phillips Petroleum Company	8. Farm or Lease Name East Vacuum Gb/SA Unit
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	9. Well No. Tract 2648 001
4. Location of Well UNIT LETTER <u>N</u> <u>1380</u> FEET FROM THE <u>west</u> LINE AND <u>1310</u> FEET FROM THE <u>south</u> LINE, SECTION <u>26</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Vacuum Gb/SA
15. Elevation (Show whether DF, RT, GR, etc.) 3919.6' GL	12. County Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Set CIBP above lower perms &amp; tst w/ submersible pump</u> <input checked="" type="checkbox"/>

## SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Recommended procedure to set CIBP above the lower perforated interval in order to plug off water production and increase oil production and test with submersible pump:

MI RU DDU. Install BOP. RIH with gauge ring, tag fluid level and record, tag TD, POOH. RIH with CIBP on wire line. Set CIBP at 4552'. RIH with submersible test pump on 2 7/8" tubing and set bottom of motor at  $\pm 4510'$ . Return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph J. Paper for W. J. Mueller TITLE Engineering Supervisor, Reserve DATE July 3, 1986

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE

JUL 7 1986

CONDITIONS OF APPROVAL, IF ANY: