DISTRIBUTION ANTA FE						Supersedes Oi	ia.
						C-102 and C-1	103
		N	EW MEXICO OIL C	ONSERVATION COMMISSION		Effective 1-1-	65
1CE							
5.6.8.					50	. Indicate Type	
AND OFFICE					<u></u>	State X	Fee
PERATOR			NO. 30-025-2	6677] 3.	State Cti & Ga A-1	.320
						\overline{mm}	
SUNDRY NOTICES AND REPORTS ON WELLS TO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.					IR. 7	Unit Agreemen	n Name East
oic X	**** []	OTHER-			v	acuum Gb/	_
Phillips Petroleum Company					G	b/SA Unit	Tract 3236
Attress of Operator					9	, Well No.	206
	001 Penl	prook Street	, Odessa, Te	xas 79762		0. Field ond Fo	006
Location of Well					1		
UNIT LETTER	·	2500	ET FROM THE West	LINE AND	- PEET PROM	Vacuum Gb	TTTTTTTTT
N 1		20	_	17.0			
North	LINE, 1	SECTION 32	TOWNSHIP	17-S RANGE 35-E	NMPM.		
mm	m	i mm	Flevation (Show wh	ether DF, RT, GR, etc.)	<u></u>	2, County	444444
		//////////////////////////////////////	3964.7 GR	,		Lea	
	77777				Oak a	Doco	
\overline{m}	CI	1 4	. D.u Ta Ialiaa	a Nama a Nama Da		Data	
				te Nature of Notice, Rep			
	NOTICE C	ck Appropriat of INTENTION	то:	SUE	SEQUENT F	REPORT OF	۲-
CRFORM REMEDIAL WO	NOTICE C			REMEDIAL WORK COMMENCE DRILLING OPNS. CABING TEST AND CEMENT	SSEQUENT F	REPORT OF	RING CASING AND ABANDONMENT
ERFORM REMEDIAL WO	NOTICE C		TO:	REMEDIAL WORK COMMENCE DRILLING OPHS	SSEQUENT F	REPORT OF	RING CASING
ERFORM REMEDIAL WO	NOTICE C		TO:	REMEDIAL WORK COMMENCE DRILLING OPNS. CABING TEST AND CEMENT	SSEQUENT F	REPORT OF	RING CASING AND ABANDONMENT
EMPORARILY ABANDON OULL OR ALTER CASING	DAK	F INTENTION	TO: PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPNS. CABING TEST AND CEMENT	X Depth	ALTE	RING CASING AND ABANDONMENT
EMPORM REMEDIAL WO EMPORARILY ABANDON ULL OR ALTER CASING OTHER OTHER Descrite ; royose, work) SEE RULE	oak	OF INTENTION	TO: PLUG AND ABANDON CHANGE PLANS variy state all pertine	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT OTHER TOTAL I	SEQUENT F	REPORT OF ALTE PLUG	RING CASING AND ABANDONMENT X Starting any propose
EMPORM REMEDIAL WO EMPORARILY ABANDON ULL OR ALTER CASING OTHER OTHER Descrite ; rotoses Work) SEE RULE	i or Completions. MI Cact at 353' Temp. c	ted Operations (Classes Drlg. St. Cmt w/40 of cmt. 70 d	PLUG AND ABANDON CHANGE PLANS variy state all pertine pudded w/12- 00 sxs C1. "H' degrees, zone	REMEDIAL WORK COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER TOtal I	Es, including es Ran 8-5/8 ocele. Communication	timated date of irc 11 sx th 1500 p	AND ABANDONMENT X Starting any propose # K-55 set as to surface
EMPORM REMEDIAL WE EMPORABILY ABANDON ULL OR ALTER CASING OTHER	i or Completion. MI Cact at 353' Temp. c place I	tus Drlg. So Cmt w/40 of cmt. 70 dd	PLUG AND ABANDON CHANGE PLANS Parly state all pertine pudded w/12- 0 sxs C1. "H' egrees, zone or to test.	REMEDIAL WORK COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER TOtal II Int details, and give pertinent dat 1/4" hole to 355'. W/2% CaCl, 1/4# F1 temp. 60 degrees, of Tested to 500# for	Ran 8-5/8 ocele. Comt streng	timated date of irc 11 sx th 1500 ps. OK	AND ABANDONMENT X Starting any propose # K-55 set as to surface
TERFORM REMEDIAL WE EMPORABILY ABANDON OULL OR ALTER CASING OTHER	A or Completion. MI Cact at 353 Temp. of place 1	tus Drlg. So cont. 70 do la hours pri	PLUG AND ABANDON CHANGE PLANS Parly state all pertine pudded w/12- 0 sxs C1. "H' egrees, zone or to test.	REMEDIAL WORK COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER TOTAL I Int details, and give pertinent dat 1/4" hole to 355'. W/2% CaCl, 1/4# F1 temp. 60 degrees, of Tested to 500# for OK Drld ahead w/7-	Ran 8-5/8 ocele. Comt streng	timated date of irc 11 sx th 1500 ps. OK	AND ABANDONMENT X Starting any propose # K-55 set as to surface
TERFORM REMEDIAL WE EMPORABILY ABANDON OULL OR ALTER CASING OTHER	A or Completion. MI Cact at 353 Temp. of place 1 NU BOP! Reached Ran 117 10% DD,	tus Drlg. So to the control of the c	PLUG AND ABANDON CHANGE PLANS Forly state all pertine pudded w/12- 00 sxs C1. "H' legrees, zone or to test. OP's and csg Running logs 14# K-55 csg 1e, 3#/sx Gi	REMEDIAL WORK COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER TOTAL I Int details, and give pertinent dat 1/4" hole to 355'. W/2% CaCl, 1/4# F1 temp. 60 degrees, of Tested to 500# for OK Drld ahead w/7-	Ran 8-5/8 ocele. Comt streng 30 minute 7/8" bit.	timated date of " csg. 24 irc 11 sx th 1500 ps. OK sxs TRLW, "H" w/5#	Starting any proposed ## K-55 set as to surface osi, cmt in 12# salt, salt, salt. Circ

Orig. Signed By

Jerry Sexton

Onortions of Approval 2,15 upper