

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S. G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-155-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
TEXACO Inc.

Address of Operator
P.O. Box 728, Hobbs, New Mexico 88240

Location of Well
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM
THE West LINE, SECTION 5 TOWNSHIP 17S RANGE 35E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
N.M. "O" State NCT-4

9. Well No.
1

10. Field and Pool, or Wildcat
Vacuum Grayburg San Andres

15. Elevation (Show whether DF, RT, GR, etc.)
3997' GR

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
ALTER OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Installed BOP.
2. Load hole w/mud.
3. Spot 100 sx. cl "H" neat 4759-4959'. Tag cmt. at 4646'. (Top of plug).
4. TOH w/tbg. to 3086'.
5. Spot 45 sx. cl "H" cmt. 3000-3100'.
6. TOH w/tbg. to 1972'.
7. Spot 10 sx. cl "H" (20') plug at surface.
8. Cut off WH. Installed marker. Clean location. Plugged and Abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed W.B. Cook TITLE Dist. Opr. Mgr. DATE 6/26/85


Signed [Signature] TITLE OIL & GAS INSPECTOR DATE AUG 12 1986

ADDITIONAL APPROVAL, IF ANY:

RECEIVED

JUL -1 1985

100-100000



LTR



Job separation sheet

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-76

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-155-1	

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		
<p>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		7. Unit Agreement Name
<p>Name of Operator TEXACO INC.</p>		8. Farm or Lease Name N.M. "O" State NCT-4
<p>Address of Operator P.O. BOX 728, HOBBS, NEW MEXICO 88240</p>		9. Well No. 1
<p>Location of Well UNIT LETTER N, 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 5, TOWNSHIP 17S, RANGE 35E, NMPM.</p>		10. Field and Pool, or Wildcat Vacuum Grayburg San Andre
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3997' GR</p>		12. County Lea

<p>6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Load hole with mud.
- Spot 200' (90 sx) cement plug from 4759'-4949' to cover perforations (4834'-79').
- Spot 100' (45 sx) cement plug from 3000'-3100' below salt section.
- Spot 100' (45 sx) cement plug from 1900'-2000' above salt section.
- Spot 20' (10 sx) cement plug at surface.
- Install marker and clean location.

ALL OPERATIONS MUST BE NOTICED 24
HOURS AHEAD TO THE DIVISION OF
ENERGY OPERATIONS FOR THE CIOJ
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W.B. Loh</u>	TITLE <u>District Operations Manager</u>	DATE <u>March 8, 1985</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
PROVED BY _____	TITLE _____	DATE <u>MAR 12 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAR 12 1965

POSTAL OFFICE