

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Record "YW"
9. Well No. 1
10. Field and Pool, or wildcard North Pearl
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A Re-entry
2. Name of Operator Yates Petroleum Corporation
3. Address of Operator 207 South 4th St., Artesia, NM 88210
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 2180 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 19S RANGE 35E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.) 3678' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission obtained from Mr. Jerry Sexton, NMOCD, Hobbs, 10-9-85, by Mr. Ray Stall to plug and abandon well as follows:

- 1) Set CIBP in 7-5/8" casing approximately 4800' and cap thru tubing with enough cement to bring cement to 4250' (50' above 7-5/8" casing stub inside 10-3/4" casing).
Cement volume required = (.215x535+.5509x55) = 55 cu ft.
 - 2) Spot 100' plug across Rustler Anhydrite @1768'.
Cement volume required = .5509x100 = 55 cu ft.
 - 3) Set 15 sx plug at surface with regulation abandonment marker.
- NOTIFY NMOCD, HOBBS, IN TIME TO WITNESS PLUGGING OPEATIONS.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNED <u>Jerry Sexton</u>	TITLE <u>Production Supervisor</u> DATE <u>10-13-85</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	
APPROVED BY _____	TITLE _____ DATE <u>OCT 17 1985</u>
CONDITIONS OF APPROVAL, IF ANY:	

RECEIVED
OCT 16 1985
OFFICE
HOBBS OFFICE