



reamer, 1-monel drill collar, 15-8" drill collars, and crossover. Reamed 665'-913'. Tripped out of hole to re-space reamers at 90' and 120'. Ran survey, hole was 5 degrees at 919' S37 W and 4 degrees at 886' S26W. Currently drilling.

RECEIVED

APR 29 1982

HOLLIS CHANCE