et.
SANTA FE Forn C-1 FILE SANTA FE, NEW MEXICO 87501 U.3.G.3. Subscription LAND OFFICE Solution OFERATOR Subscription SUNDRY NOTICES AND REPORTS ON WELLS Subscription Image: Subscription Subscription Subscrint Subscrint
FILZ SANTA FE., NEW MEXICO 87501 Revised U.S.G.S. Subscription Subscription Subscription OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS Subscription Subscription SUNDRY NOTICES AND REPORTS ON WELLS Subscription Subscription Subscription Index of Subscription Subscription Subscription Subscription Index of Subscription Subscription Subscription Subscription Index of Operator Subscription Subscription Subscription Index of Operator Subscription Subscription Subscription Amoco Production Company Subscription Subscription I. Address of Operator Subscription Subscription
U.S.G.S. Sul Indicate Type of Lesse LAND OFFICE State OPERATOR State SUNDRY NOTICES AND REPORTS ON WELLS State Off & Gas Lease No. Iso not use this promy frame frame proposals to chill on to decert and plug alcan to A dipperature acservoire. Vistor Company I. State OTHER. - will State other. 2. Name of Operator OTHER. Amoco Production Company 8. Farm of Lease Name J. Address of Operator Snyder Ranches
LAND OFFICE State Fo OFERATOR SUNDRY NOTICES AND REPORTS ON WELLS State State (DO NOT USE THIS FORM FOR PROPOSES TO CHILL ON TO DEEPEN OR PLUG ANCK TO A DIFFERENT RESERVOIR. VIII (VIII) VIII) 1. - OTHER OTHER VIIII FOR DUCH PROPOSES.) 2. Name of Operator OTHER VIIII OTHER VIIII FOR DUCH PROPOSES.) 3. Address of Operator 8. Form or Lease Name Snyder Ranches
OPERATON Sumpression SUNDRY NOTICES AND REPORTS ON WELLS Sumpression Interminent of property of the property
SUNDRY NOTICES AND REPORTS ON WELLS (DD HOT USE THIS FORM FOR PROPOSILS TO CHILL ON TO DEEPEN OF PLUG AICH TO A DIFFERENT ALSERVOIR. 1. - ONL State Contraction For FERMIT - " (FORM C-1011 FOR DUCH PROPOSILS.) 2. Name of Operator Amoco Production Company 3. Address of Operator 3. Address of Operator
ORE WELL OTHER-
well [] others 2. Name of Operator 8. Farm of Lease Name Amoco Production Company 8. Farm of Lease Name 3. Address of Operator 9. Farm of Lease Name
Amoco Production Company 8. Form of Lease Name Snyder Ranches
J. Address of Operator
, Address of Operator
P. U. BOX 68, HODDS, New Mexico 88240
A. Location of Well 10. Field and Pool, or Wildow
LINE AND CINE TROW
THEEast 8 19-S 35-E
THE East 8 19-S 35-E NUCLE
ALLININ 3838.1 GL
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
- NOTICE OF INTENTION TO:
SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK
TEMEORANU ADANDON ADANDON ADANDON ALTERING CASING
COMMENCE DRILLING OPNS.
PULL OR ALTER CASING L CHANGE PLANS CASING TEST AND CEMENT JOB
attempt to complete in Wolfcamp
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any pr works SEE RULE 1103.

Propose to cement squeeze intervals 9662'-9669' and 9672'-9688', and perforate intervals

10,518'-44', 10,637'-43', and 10703'-12' per the following:

Move in service unit and pull tubing and packer. RIH with cement retainer and set retainer at 9525". Squeeze intervals 9662'-9688' with 150 sx class H containing .6% Halad 9 fluid loss additive. (Previous squeeze across these intervals had a max. pressure of 3800 psi at .5 BPM. An average injection rate of 2.7 BPM with a max pressure of 4250 psi was recorded after acid stim. run 1-6-83.). WOC. Drill out cement and test squeeze to \leq 1000 psi. Circulate casing with clean brine from PBTD (10,714") to surface. Perforate the Wolfcamp intervals 10,518'-10,544'-10,637'-10,643' and 10,703'-10,712', (41' met) with 4 JSPF utilizing a 3-1/8" centralized hollow carries casing gun with 90° or 120° phasing. RIH with 2-3/8" tubing, packer, 8 joints of tailpipe with seating nipple on bottom. Land tailpipe at 10,490'. Do not set packer. Run base gamma ray/temperature survey. Drop tailpipe down to 10,712'. Du not set packer. Spot 250 gals 15% MCA acid down tubing to wash and soak perforation. Pull up and set packer at 10,250'. Land tubing at 10,490'. Continue with acid treatment as follows: Pump 1500 gals of 15% MCA acid at 2-3 BPM. Pump 6500 gals of 15% MCA acid at 2-3 BPM with a max. surface pressure of 5000 psi. Tag acid with RA material. Flush to perfs with 47 bbl of 0+4-NMOCD,H 1-HOU 1-W. Stafford, HOU 1-CMH

alanco Karly M. X lerring		Assist. Admin. Analyst	1 10 00
	TITLE	ASSIST. Admin. Analyst	DATE 1-19-83
ORIGINAL SIGNED BY	TITLE		JAN 20 1983

clean brine. Run after treatment gamma ray/temperature survey. Flow back load. Swab if necessary. AFter the load is fully recovered, shut the well in and run a dip in bottom hole pressure test. Max. pressure expected 4600 psi. Take gradient stops at 3000',6000',8000', 9000', 10,000', and 10,600'. Record at surface pressure. A supplemental brief will follow, if necessary, to place the well on production following the results of the swab test and pressure tests.

> > 1.1.1

RECEIVED

JAN 1 9 1983

O.C.D. HOBES GERICE