

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28018
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	A4096
7. Lease Name or Unit Agreement Name	NEW MEXICO "DD" STATE
8. Well No.	6
9. Pool name or Wildcat	SCHARB - BONE SPRINGS

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	J & G Enterprise Ltd. Company
3. Address of Operator	P. O. Box 100, Artesia, NM 88210
4. Well Location	Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line
Section 4	Township 19S Range 35E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3902 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5-7 CIRC Salt Gel Mud @ 3000'. Pump 25 sx. "C" 5000' - 4780'.
- 5-7 Pump 25 sx "C" from 4000'. WOC tag plug @ 3860' (9 5/8 shoe)
- 5-7/8 Cut & pull 5 1/2" csg. from 3310'.
- 5-8 Circ. salt gel mud. Pump 50 sx "C" from 3364' WOC tag @ 3205' (5 1/2" stub).
- 5-8 Pump 40 sx "C" from 425' - 325'.
- 5-8 Pump 10 sx. "C" 20' - surface.
- 5-8 Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Larry Murray

TITLE

Agent

DATE 5/30/97

TELEPHONE NO.

TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY

Larry M. Hill

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

FC CW

ep