

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

1a. Indicate Type of Lease State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-1546

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State MX
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>710</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>19-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Scharb Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3783.3' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> attempt Bone Springs completion	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon the Wolfcamp and attempt completion in the Bone Springs per the following:

Release packer set at 10,329'. Drop down and release the bridge plug at 10,575'. POH. RIH with a wireline set CIBP at 10,250' and cap with 35' cement. Perforate the Bone Springs intervals 9462'-9472' with 2 JSPF utilizing a 3-3/8" centralized hollow carrier casing gun with 90° or 120° phasing. RIH with 2-3/8" tubing, packer, and 1 jt. of tailpipe with a seating nipple on bottom. Set packer at 9370'. Swab test well. If well will not flow, proceed with Bone Springs stimulation as follows:

- Run base gamma ray /temperature survey.
- Pump 1500 gals of 15% NE HCL acid at 2-3 BPM. Tag all acid with R/A material.
- Flush to perms with 40 bbls of brine.
- Run after treatment gamma ray/temperature survey.

Swab back load and evaluate production.

* NMOC Order No. R-2589-C makes this location orthodox for a Scharb Bone Springs Completion.

0+4-NMOC, H. 1-HOU R.E.Ogden, Rm. 21.150 1-F.J.Nash, HOU Rm 4.206 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Herring TITLE Administrative Analyst DATE 6-17-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 20 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 17 1993
C.C.D.
HOBBS OFFICE