

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Box 1980, Artesia, NM 88210

DISTRICT III
P.O. Box 1980, Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28397
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 6008-1
7. Lease Name or Unit Agreement Name Queen B Lee State
8. Well No. 1
9. Pool name or Wildcat Scharb Queen

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)


Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	Name of Operator J&G Enterprise Ltd., Co.
Address of Operator PO Box 100, Artesia, Nm 88210	Well Location Unit Letter M : 519 Feet From The S Line and 519 Feet From The W Line Section 3 Township 19S Range 35E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3878.6	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Move to new zone <input checked="" type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP on wire line w/35' cement on top @ 9407'
2. Load hole w/2% kcl water
3. Run bond log from 5000' to 3300'
4. Perforate Queen zone @ 4642-4650'
5. Treat w/1500 gal. 15% NEFE acid
6. Swab acid back until oil appeared
7. Release packer POH lay packer down Run tubing - pump & rods.
8. Set pumping unit. Commence pumping. 5/27/95

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 	TITLE President	DATE 5-31-95
TYPE OR PRINT NAME J.T. Jackson		TELEPHONE NO. 505-746-9680

This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 06 1995

Handwritten: Scharb BS

RECEIVED

JUN 6 1964

OFFICE
OF THE
ATTORNEY GENERAL

1964 JUN 6