

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P.O. Box 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
-

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER Dry hole
--------------------------------------	-----------------------------------	----------------

XXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXX  
XXXXXXXXXXXXXXXXXXXXXXXXXXXX

7. Unit Agreement Name
-

2. Name of Operator
Read & Stevens, Inc.

8. Farm or Lease Name
Blackmar

3. Address of Operator
P.O. Box 1518, Roswell, NM 88201

9. Well No.
1

4. Location of Well
UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE. SECTION <u>5</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> NMPM

10. Field and Pool, or Wildcat
Wildcat

5. Elevation (Show whether DF, RT, GR, etc.)
3789.6' GL

12. County	XXXXXXXXXXXXXXXXXX
Lea	XXXXXXXXXXXXXXXXXX

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP @ 4800', spot 35' of cmt on plug w/dump baller.
- 2) Circulate hole with mud.
- 3) Spot 25sx plug from 4500' to 4400' across 8 5/8" casing shoe @ 4450'.
- 4) Cut csq @ +2600', pull csq, spot 25sx plug @ 2550' to 2650' across csq stub.
- 5) Spot 100' plug 1950' to 2050', 35sx cmt, top of salt plug.
- 6) Spot 10sx surface plug w/dry hole marker.
- 7) Clean location and prep for inspection.

OPERATOR MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR PLUG BACK TO A DIFFERENT RESERVOIR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Hubbel TITLE Drilling & Production Manager DATE 8-30-84

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE 9-1-84

CONDITIONS OF APPROVAL, IF ANY: