

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
El , Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28945
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name MESCALERO RIDGE C
8. Well No. 1
9. Pool name or Wildcat SCHARB BONE SPRINGS
10. Elevation (Show whether DF, RKB, RT, GR, etc.) ZERO AT KB (3857')

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator MOBIL PRODUCING TX & NM INC.
3. Address of Operator BOX 633, MIDLAND, TX 79702

4. Well Location Unit Letter N : 2121 Feet From The WEST Line and 801 Feet From The SOUTH Line
Section 17 Township 19S Range R35E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>
OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:
REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P & A (WITHOUT CASING RECOVERY)

- MIRU WO UNIT. UNSEAT PUMP. POOH W/RODS & PUMP. NU BOP, TEST. RELEASE TAC, POOH W/TBG & TAC.
- SET CIBP @ +OR- 9700' & 50' CMT CAP.
- PERF SQUEEZE HOLES 4 SPF, 4150-4152'.
- SET CMT RETAINER @ +OR-4050', SQUEEZE 45 SKS BENEATH RETAINER-BEHIND 5 1/2" & DUMP 5 SKS ON RETAINER.
- CIRC WELL W/10 PPG GELLED BRINE.
- PERF SQUEEZE HOLES 4 SPF, 450-452'.
- CIRC 210 SKS BETWEEN 8 5/8-13 3/8 (INCLUDES 66 SKS FOR ALSO CIRC 8 5/8-5 1/2"). Fill 5 1/2" w/46 sks. to surface.
- Cut csg 3' below surface, weld on plate and P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley Todd

TITLE

DATE 11-29-89

TYPE OR PRINT NAME SHIRLEY TODD

TELEPHONE NO. 688-2585

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

DEC 04 1989

CONDITIONS OF APPROVAL, IF ANY: