

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-28945</u>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Mescalero Ridge C
8. Well No. <u>1</u>
9. Pool name or Wildcat Scharb Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Mobil Producing TX & NM Inc.	
3. Address of Operator c/o Mobil Exploration & Producing US, Inc. P. O. Box 633, Midland, Texas 79702	
4. Well Location Unit Letter <u>N</u> : <u>2121</u> Feet From The <u>West</u> Line and <u>801</u> Feet From The <u>South</u> Line Section <u>17</u> Township <u>19S</u> Range <u>35E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) Zero at KB: 3857'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PA with casing Recovery

- MIRU Wo unit. Unseat pump, POOH w/rods & pump. NU Bop test. Release TAC, POOH w/tbg.
- Set CIBP @ $\pm 9700' + 50'$ (5sk) cmt cap. Circ well w/10 ppg gelled brine.
- Cut $5\frac{1}{2}"$ K-55 csg @ $\pm 5600'$, POOH w/csg.
- Set cmt plug (3lsk) over cut $5\frac{1}{2}"$ 5525-5675'. Tag plug.
- Set 150' (41 sk) cmt plug over 8 5/8 shoe 4025-4175'. Tag plug.
- Set 100' (27sk) cmt plug at top of salt 1600-1700'.
- Perf @450-54' 4SPF, set retainer C350'. Circ 195 sks cmt between 8 5/8 - 13 3/8", leave 25' on retainer.
- Set 100' (27sk) cmt plug at surface. But csg 3' below ground, weld on cap and P & A marker

Procedure discussed with Paul Koats (NMOCD) on 9-19-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Shirley Todd

TITLE

DISTRICT I SUPERVISOR

DATE 10-12-89

TYPE OR PRINT NAME

Shirley Todd

915-688-2585
TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JEFFY COTTON
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE WELL TO BE APPROVED.

OCT 16 1989

RECEIVED

OCT 16 1983

OCD
HOBBS OFFICE