## Equipment Specifications and Installation b clions

- All connections on the BOP stock shall be flanged or balted ring clamp of comporable rating.
- All flonges to be API 6B or 6BX and ring gaskets shall be API RX or BX. 3.
- All drilling spools are to be forged steel construction. Spools constructed from pipe are not acceptable. 4.
- The fill-up line shall not be connected to any side outlet below the uppermost preventer.
- 5. Replacement parts for the BOP equipment shall be obtained from the original manufacturer. 6.
- BOP stock shall be properly braced to rig substructure by turnbuckled lines or rods.
- 7. Connections on the kill line, choke lines and choke monifold:
- May be threaded, welded, flanged or balted ring clamp.
  Shall be either flanged or balted ring clamp of comparable rating.
- 8. All gote volves must be equipped with hand wheels. 9.
- Chake and kill lines are to be scamless steel pipe having a minimum working pressure that is based on 80% of the API minimum internal yield pressure rating of that pipe. 10.
- The kill line shall not be used as a fill-up line.
- 11. All choke lines must be as straight as possible with no abrupt bends or turns,
- 12. All choke lines are to be securely anchored. 13.
- Steel hose (chicksons) ore not to be used in ony part of the choke monifold.
- The occumulator unit and master set of controls shall be located at ground level, a minimum of 14. from the well bore. The remote set of controls is to be located near the drillers position on the rig floar. All hydroulic lines between the occumulator and any hydroulically operated device shall be of seamless steel 15.
- pipe ond swing joints. Rubber hoses are not permitted. Short lengths of high pressure hose are permitted in lines connecting the remote station to the valve actuating cylinders on the master control unit. Housing and heating should be provided for accumulator, blawout preventers and chake manifold where condi-16.
- tions worront.
- 17. All drill string blowout prevention equipment must be maintained in good operating condition and stored in an orderly condition on the rig floor.
- Operating wrenches for the drill string BOP equipment are to be kept in full view near the driller's position. 19. Controctor to make no connection to casing head side outlets except by orders of Pzt.
- 20. Keep on rig: (a) One spore set of pipe roms, complete with packing rubbers for each size of drill pipe in use.
  - (b) Replacement parts for all manual adjustable chokes along with the necessary tools for changing parts.
- When a rotating head is in use on the BOP stock, dresser sleeve connections in the flowline are not permitted. 21. 22. Hond wheels and extensions (outside the substructure) shall be installed for operating the locking screws on all rom preventers and hydraulically operated gate valves on the choke and kill lines. If the installation of these extensions create a safety hazard or far some unavoidable reason cannot be properly installed, a hand crank or wrench should be readily available to operate the locking screws.
- 23. When a wear bushing is required, only the lock-in type shall be used.
- Water lines and valves shall be connected and ready for use on all internal combustion engine exhausts. 24.
- The cellar is to be kept jetted and the preventer stack and chake manifold washed down at all times. 25.
- All volves are to be lubricated at regular intervals. 26.
- 27. All volves are to be clearly identified as being open or closed.
- 28. Proper alignment of the rig with the center line or the BOP stack and casing shall be maintained at all times
- 29. All flonge bolts on the stock, kill line and choke manifold should be tightened at least once each week.

## RECEIVED OCT 1 0 1985 O.C.D. HOBES CHARCE