

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-29856</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Shipp
8. Well No. <u>37</u>
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Charles B. Gillespie, Jr.	
3. Address of Operator P.O. Box 2557 - Midland, Texas 79702	
4. Well Location Unit Letter <u>B</u> : <u>550</u> Feet From The <u>F-N-L</u> Line and <u>2310</u> Feet From The <u>F-E-L</u> Line Section <u>11</u> Township <u>17-S</u> Range <u>37-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 5-1/2" Cast Iron Bridge Plug at 11,450' and cap with 35' cement.
- 2) Load hole with mud.
- 3) Spot 100' cement plug at Abo-8722'.
- 4) Spot 150' cement plug at Whipp Stock at 8250' 75' above 75'.
- 5) Spot 100' cement plug at 5-1/2" stub approximately 7000' 50' in and 50' out and tag.
- 6) Spot 100' cement plug at Glorietta 6744'.
- 7) Spot 100' cement plug at 8-5/8" shoe 4498' and tag.
- 8) Spot 100' cement plug at 13-3/8" shoe 465'.
- 9) 15 sacks cement plug at surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maklarovich TITLE Supervisor DATE 2-15-93

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY [Signature] DISTRICT I SUPERVISOR FEB 15 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
FEB 15 1993
OCD HONRS OFFICE